

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508000
Fax: 6546 8156

Our Job Ref No : 305472575
Date : 10/06/21

FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SH 7218B

Date of Accident : 07/06/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: NTUC --- SMQ4452J
- The finalized amount shall be:
 - Spare Parts after List discount NIL
 - Labour Charges \$630.00
 - Total for Part-By-Part Repair Cost** \$630.00
 - Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : NAZ
Date : 15/6/2021

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 10.06.2021
Time: 11:26:02
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305472575
REGN NO : SH 7218B
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 07.10.2016
DATE/TIME IN : 07.06.2021 12:45
ACCIDENT DATE : 07.06.2021

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 PB	PANEL BEATING-SH 7218B	350.00	/
0001 SP	SPRAYPAINT CHARGE	250.00	/
0002 L	R/I REVERSE SENSORS	30.00	/
		SUB-TOTAL :	630.00

TOTAL : 630.00


MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LKK -

DATE: 8-Jun-21

INSURANCE: NTUC (L/S)

MODEL: Toyota Prius

MVA: LIM T S

VEHICLE NO.: SH 7218B

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$458.60
	Rear Bumper Lower Cover-Black	1		\$552.60
	Rear Bumper Clips	10	\$2.20	\$22.00
				SUB TOTAL
				\$1,033.20
				LESS 25%
				\$258.30
				DISCOUNTED TOTAL
				\$774.90
	Reverse Sensor	1		\$135.70
				NETT TOTAL
				\$135.70
				TOTAL SPARE PARTS
				\$910.60
	Labour Charge			
	Panel Beating			\$400.00
	Spray Painting Charge			\$300.00
	Remove/Refix Reverse Sensor			\$120.00
				TOTAL LABOUR
				\$820.00
				ESTIMATE TOTAL
				\$1,730.60

XR
XSVC
XSVC

XSVC

350
250
30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA2 LKK
8/6/2021 @ 16:50
L/S
2 Days
AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: