

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

AUTOMOBILE INSPECTION REPORT



ACTOMOBILE INCITED TO INT						
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC21006608/Ntce2						
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556				17-06-2021		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLL 5190X	Veh. Ir	spected	SHB 2083S	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1134345-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	10/06/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	c.c		1798	
	Engine No.	HIDDEN	Year o	f Reg.	2020	
	Chassis No.	JTDKB3FU803092679	Colou	r	YELLOW	
	Odometer	124195	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST		5 mm	
	L/H Front Tyre	195/65 R15	WEST		5 mm	
	R/H Rear Tyre	195/65 R15	WEST		5 mm	
	L/H Rear Tyre	195/65 R15	WEST		5 mm	
4.	_					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/06/2021		tion Date	10/06/2021	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					