

|   |        |      |             |
|---|--------|------|-------------|
| 1 | of 2 ? | 100% | Find   Next |
|---|--------|------|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                   |                          |            |
|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|--------------------------|------------|
| SMRT AUTOMOTIVE SERVICES PTE LTD                                                                                                       |                                                                                   | Ref: CS/SMR21006613/Kuf3 |            |
| 60 WOODLANDS INDUSTRIAL PARK                                                                                                           |                                                                                   | Date: 11/06/2021         |            |
| E4SINGAPORE 757705                                                                                                                     |                                                                                   | Code: SMR                |            |
| 1. Policy Particulars :- THIRD PARTY CLAIM                                                                                             |                                                                                   |                          |            |
| Insured Veh.                                                                                                                           | SG 1103T                                                                          | Veh. Inspected           | YQ 1839E   |
| Policy No.                                                                                                                             |                                                                                   | Coverage (\$)            | 0.00       |
| Claim No.                                                                                                                              | BUS/05/21/1022                                                                    | Excess (\$)              | 0.00       |
| Assign From                                                                                                                            | HUA YEN                                                                           | Assign Date              | 11/06/2021 |
| 2. Vehicle Particulars & Condition                                                                                                     |                                                                                   |                          |            |
| Make & Model                                                                                                                           |                                                                                   | c.c                      | 0          |
| Engine No.                                                                                                                             | HIDDEN                                                                            | Year of Reg.             |            |
| Chassis No.                                                                                                                            |                                                                                   | Colour                   |            |
| Odometer                                                                                                                               | -                                                                                 | Steering                 |            |
| Brakes                                                                                                                                 |                                                                                   | Modification             |            |
| General                                                                                                                                |                                                                                   |                          |            |
| 3. Conditions of Tyres                                                                                                                 |                                                                                   |                          |            |
|                                                                                                                                        | Size                                                                              | Make                     | Balance    |
| R/H Front Tyre                                                                                                                         |                                                                                   |                          | mm         |
| L/H Front Tyre                                                                                                                         |                                                                                   |                          | mm         |
| R/H Rear Tyre                                                                                                                          |                                                                                   |                          | mm         |
| L/H Rear Tyre                                                                                                                          |                                                                                   |                          | mm         |
| 4. Description of Damages                                                                                                              |                                                                                   |                          |            |
|                                                                                                                                        |                                                                                   |                          |            |
| 5. General Information                                                                                                                 |                                                                                   |                          |            |
| Accident Date                                                                                                                          | 20/05/2021                                                                        | Inspection Date          | 11/06/2021 |
| Survey held at                                                                                                                         | RS AUTO SERVICES<br>160 SIN MING DRIVE SIN MING AUTOCITY # 06-01 SINGAPORE 575722 |                          |            |
| 5a. Remarks                                                                                                                            |                                                                                   |                          |            |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                   |                          |            |