

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	Re	ef:	CS3/ASM21006622/Kqce2	
	8 SHENTON WAY TOWERSINGAPOR	Da	ite:	24/06/2021		
	ATTN: NG STACE	(Co	de:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SFG 2796R	Veh. Inspected		SGH 5816E	
	Policy No.	GA551515	Coverage (\$)		0.00	
	Claim No.	S1M03BEN	Excess (\$)		0.00	
	Assign From	NG STACEY	Assign Date		11/06/2021	
2. Vehicle Particulars & Condition						
	Make & Model	NISSAN SYLPHY (A)	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	MNTBBAB17Z0033083	Colour		METALLIC SILVER	
	Odometer	33275 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/50 R16	BRIDGESTONE		7 mm	
	L/H Front Tyre	195/50 R16	BRIDGESTONE		7 mm	
	R/H Rear Tyre	195/50 R16	BRIDGESTONE		7 mm	
	L/H Rear Tyre	195/50 R16	BRIDGESTONE		7 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT BODY AND UNDERCARRIAGE.					
5.	5. General Information					
	Accident Date	06/06/2021	Inspect Date / Tim	ne	11/06/2021 (01:00 PM)	
_	Survey held at KUM CHEW MOTOR WORKSHOP					
	160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722					
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					

Report Ref No. CS3/ASM21006622/Kqce2

Inspected By

KONG SENG CHEONG

K.K.LAU CPT(RET)

Licensed Appraiser BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser