ASSIGNMENT

From: Date:	Veh No: GBA 8004H. Yr Regn: 2017, May.
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Nissan Cabetar. c.c 2953
at Workshop m/s	Make: Nrissan Cabelar c.c 2953 Colour While A/C: Insured/Std/NI/NA
of	Sp.Reading /58257 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: JN/SC2F24Z0855684
Claims No.	Gen. Cond/ Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
Rest degrade,	Tyre Size: F: 195 R15 R: 195 R45
(Policy Condition)	R: 195 P45.
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Condo
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bai. q mm L/Bai.
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 11/06/21.
Lum Sum: % 3 Val.: Yes or No	Survey held at Rydes.
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	The U/C / Chassis frame / Body Structure affected due to collision.
Duto.	The O/O / Chassis frame / Dody chattan
Date / Time Action / Instruction 1 P Lon Pae.	and a small come of the same beautiful
	Ann contract with the later in the angle region of the bounding the Angle of the second
m∨ :	1 34 SSLA ELSH - L L VERREUR CON CLUT (III-III
PV:	
Nett:	
E AUCUST IN IIS	
Date/Time, File Pass to? : Prell. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fe	
*	: Interview (\$) Photos
Report Formet:	: Tech. Invs (3) Others
Lump Sum / LBJ: (3	: Weel end (\$
	70781