



AIG- OD CLAIM
SURVEY: 14/06/21
LVK - STEVE

VEHICLE NO : SMZ 5052 B

MODEL : KIA/CERATO 1.6 A EX

WIP : 34559

Material	:	\$	<u>5,812.20</u>
Labour	:	\$	<u>3,500.00</u>
Sub-Total	:	\$	<u>9,312.20</u>
Less 2% Disc	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>9,012.20</u>
GST 7%	:	\$	<u>630.85</u>
Grand Total	:	\$	<u>9,643.05</u>
Finalise By/Date : <u>LVK on 02/07/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 07 WORKING DAYS + 2 days (wk.end)

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 14/06/2021	Cust No/Name	LCV14095/ TASK COMM ENGINEERING PTE LTD
	Reg No/Reg Date	SMZ5052B / 29/04/2021
	Date In/Mileage	11/06/2021/ 2044
	Chassis/Package	KNAF3416MM510090C /#
	Engine No	G4FGLH711927
	Make/Model	KIA/CERATO 1.6 A EX G730
	Colour/Trim	4SS / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	02/07/2021/ 12:21	BLK	884 / Lauro Songcuan	34559

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT BUMPER, FRONT LH FENDER , FRONT LH DOOR				1000.00 ✓
E PNT98000 SPRAY PAINT ON FRONT BUMPER, FRONT LH FENDER, FRONT LH DOOR & BODY KIT				1400.00 ✓
E PNT88000 REMOVE & REPLACE BODY KIT				80.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				120.00 ✓
M SUNDRY TRANSFER FRONT LH RIM INCLUDING BALANCING				30.00 ✓
E PNT88000 TRANSFER FRONT LH DOOR ATTACHMENT TO NEW PANEL				120.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY FRONT LH SPORT RIM				380.00 ✓
A 90000001 RENEW FRONT UNDER CARRIAGE → <i>Supp</i>				200.00 X
X EXC INSURANCE EXCESS				-300.00
X NEW K3 2020 BODY KIT ✓	1.00	1721.00	00.00	1721.00 ✓
X LAMP ASSY-HEAD,LH ✓	1.00	1219.00	20.00	975.20 ✓
X PANEL-FENDER,LH ✓	1.00	430.00	20.00	344.00 ✓
X PANEL ASSY-FRONT DOOR,LH ✓	1.00	1277.00	20.00	1021.60 ✓
X GUARD ASSY-FRONT WHEEL,LH ✓	1.00	95.00	20.00	76.00 ✓
X MOULDING ASSY-FRT DR FRAME,LH ✓	1.00	37.00	20.00	29.60 ✓
X COVER-FR BUMPER ✓	1.00	633.00	20.00	506.40 ✓
X LAMP ASSY-SIDE REPEATER,LH ✓	1.00	143.00	20.00	114.40 ✓

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 14/06/2021	<table> <tr> <td>Cust No/Name</td><td>LCV14095/ TASK COMM ENGINEERING PTE LTD</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMZ5052B / 29/04/2021</td></tr> <tr> <td>Date In/Mileage</td><td>11/06/2021/ 2044</td></tr> <tr> <td>Chassis/Package</td><td>KNAF3416MM510090C /#</td></tr> <tr> <td>Engine No</td><td>G4FGLH711927</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G730</td></tr> <tr> <td>Colour/Trim</td><td>4SS / WK SATURN BLACK</td></tr> </table>	Cust No/Name	LCV14095/ TASK COMM ENGINEERING PTE LTD	Reg No/Reg Date	SMZ5052B / 29/04/2021	Date In/Mileage	11/06/2021/ 2044	Chassis/Package	KNAF3416MM510090C /#	Engine No	G4FGLH711927	Make/Model	KIA/CERATO 1.6 A EX G730	Colour/Trim	4SS / WK SATURN BLACK
Cust No/Name	LCV14095/ TASK COMM ENGINEERING PTE LTD														
Reg No/Reg Date	SMZ5052B / 29/04/2021														
Date In/Mileage	11/06/2021/ 2044														
Chassis/Package	KNAF3416MM510090C /#														
Engine No	G4FGLH711927														
Make/Model	KIA/CERATO 1.6 A EX G730														
Colour/Trim	4SS / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	02/07/2021/ 12:21	BLK	884 / Lauro Songcuan	34559

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X AIR DUCT-FR BUMPER,LH ✓	1.00	14.00	20.00	11.20 ✓
X BRACKET-FR BUMPER UPR SIDE MTG ✓	1.00	22.00	20.00	17.60 ✓
X ORNAMENT-KIA NO.115 ✓	1.00	32.00	20.00	25.60 ✓
X BLACK TAPE-FR DR RR,LH ✓	1.00	13.00	20.00	10.40 ✓
X GARNISH-RADIATOR GRILLE	1.00	38.00	20.00	30.40 X
X MOULDING-FRONT BUMPER,LH	1.00	36.00	20.00	28.80 X
X MIRROR ASSY-OUTSIDE RR VIEW,LH	1.00	559.00	20.00	447.20 X
X STRUT ASSY-FR,LH ?	1.00	280.00	20.00	224.00 ?
X ARM COMPLETE-FR LWR,LH → Supp.	1.00	286.00	20.00	228.80 X

Z TEXT

OD CLAIM - AIG
 DOA: 11.06.2021
 SURVEY: STEVE (LKK) 14/06/2021
 08 DAYS

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	5,812.20	Nett	9,012.20
Labour	3,070.00	7% GST on	630.85
Standard Menu	0.00		
Specialist Job	380.00	Total Payable	9,643.05
Diagnostics Job	0.00		
Sundry/Others	-250.00		
Total(w/o GST)	9,012.20		



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMZ 5052 B

<u>Materials</u>		<u>Cost \$</u>
1	Garnish- Radiator Grille	38.00 / BR
2	Moulding- Front Bumper, LH	36.00 / CVT
3	Mirror Assy- Outside RR View, LH	559.00 / BR
4	Arm Complete- FR Lwr, LH	286.00 / BT
		919.00
20% Discount		183.80
		735.20
<u>Labour</u>		
1	Renew Front Under Carriage	200.00 /
		935.20
7% GST		65.46
Total		1,000.66

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens
Tel. # 6568 4658

CAR NO: SMZ5052BWIP: 34559

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	MIRROR ASSY - OUTSIDE RR VIEW, LH	? / SUPP		✓ OR	82610M6490
2	MOULDING ASSY - FRt DR FRAME, LH	? / SUPP		✓ MC	82850M6000
3	GARNISH - RADIATOR GRILLE	? / SUPP		✓ OR	86370M6000
4	MOULDING - FRONT BUMPER, LH	? / SUPP		✓ CM	86595M6000
5		? / SUPP			15/6/21
6	REAR Front under carriage & 200	? / SUPP			
7		? / SUPP			
8	CRASH MEMBER	? / SUPP			
9	LH Side Lower Arm Assy	? / SUPP		✓ BT	25/6/21
10	LH Side Shock Absorber	? / SUPP		✓ BT	25/6/21
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: CERATO 1.6 A EXSURVEYOR: STEVE LK

Work Order: R001458
 License: smz 5052 b
 Technician: 810119 kfsan
 Mileage: 2045
 Date: 21.6.21 11:38



Kia : Cerato/Forte : 2019- (BD/BDm) : without Independent Rear Suspension : Rest of World

Front : Left

Actual	Before	Specified Range
-1°41'*	-1°41'*	-0°53' 0°07'
4°38'	4°38'	4°00' 5°00'
0°36'*	0°36'*	-0°03' 0°09'
13°50'	13°50'	13°30' 14°30'
12°09'*	12°09'*	12°37' 14°37'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°56'*	-0°57'*	-0°53' 0°07'
5°16'*	5°16'*	4°00' 5°00'
0°24'*	0°24'*	-0°03' 0°09'
13°40'	13°40'	13°30' 14°30'
12°43'	12°43'	12°37' 14°37'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°45'	-0°44'	
-0°38'	-0°38'	
0°11'	0°10'	
1°00'*	0°59'*	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-0°45'	-0°45'	-1°42' -0°42'
0°00'	0°00'	-0°02' 0°16'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°47'*	-1°47'*	-1°42' -0°42'
0°21'*	0°21'*	-0°02' 0°16'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
1°03'	1°02'	
0°21'	0°20'	-0°04' 0°32'
-0°11'	-0°10'	

* This value is not within specification. Tire wear, handling and safety problems may result.

Work Order: R001459
License: SMZ5052B
Technician: 214 THAM,
Mileage: 2044
Date: 21.6.21 16:08

Refer (2)

Kia : Cerato/Forte : 2019- (BD/BDm) : without Independent Rear Suspension : Rest of World

Front : Left

Actual	Before	Specified Range
-0°32'	-0°32'	-0°53' 0°07'
5°07'*	5°11'*	4°00' 5°00'
0°03'	0°06'	-0°03' 0°09'
14°40'*	14°28'	13°30' 14°30'
14°08'	13°56'	12°37' 14°37'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°25'	-0°26'	-0°53' 0°07'
5°24'*	5°23'*	4°00' 5°00'
0°04'	0°01'	-0°03' 0°09'
17°29'*	18°01'*	13°30' 14°30'
17°03'*	17°35'*	12°37' 14°37'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°07'	-0°07'	
-0°17'	-0°12'	
-2°48'	-3°33'	
0°07'	0°06'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°12'	-1°12'	-1°42' -0°42'
0°04'	0°04'	-0°02' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°23'	-1°23'	-1°42' -0°42'
0°13'	0°13'	-0°02' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°11'	0°11'	
0°17'	0°17'	-0°04' 0°32'
-0°04'	-0°04'	

* This value is not within specification. Tire wear, handling and safety problems may result.



HOME

Online



CERATO/FORTE../2021/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



ICU



CLU



IBU-SMK

3/9

System	Status	Result
ENGINE		-
AT		-
ABSESC	Success of Erasing Memory.	Good
AIRBAG		-
EPS		-
IBU-BC M		-

System	DTC	Description	State
--------	-----	-------------	-------

S/W Ver.

M-E-K-01-00-0248

VCI Ver.

02.54

ECU Ver.

M-E-K-01-00-0189

OS Ver.

Android 10



HOME

Online



CERATO/FORTE../2021/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



9/25

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IBU-BC M	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0248

VCI Ver.

02.57

ECU Ver.

M-E-K-01-00-0189

OS Ver.

Android 10



HOME

Online



CERATO/FORTE../2021/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Save



System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IBU-BC M	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No Current DTC

S/W Ver.

M-E-K-01-00-0248

VCI Ver.

02.57

ECU Ver.

M-E-K-01-00-0189

OS Ver.

Android 10