

ASS. FEE:

REF: CS/MSG 21006657/DVJ3

ASSIGNMENT

CUB Jan 2027

From: _____ Date: _____

Estimate Cost: _____

OD / L / P / RES / OD RES / EVA / NV / MV

To Insp Vehicle No: _____

at Work in m/s _____

of _____

Insurance _____

Policy No _____

Claimed to _____

Sum Insured _____

Excess: _____

(Check Record)

Make of Vehicle _____

(Police Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. of Market Value: _____

IDAC Accident Report _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repair: _____

6

days

Res.: Yes or No

Lump Sum _____

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

MSG SKV 788P

Veh No: 8H1A9479T

Vt Regn: Jan / 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius

DD 1798

Colour: Yellow

A/G: Insured / Std / RI / NA

Sp. Reading: 361039

T/Radio: Insured / Std / RI / NA

Eng/No: 22R2B88179

C/No: JTDKB3FU703078157

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: RH / L / STD A/Rim or

Tyre Size: F: 195 / 65 R 15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PR / SUGAI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal: 5

mm

R/Bal: 5

mm

L/Bal: 5

mm

L/Bal: 5

mm

D.O.A: 11/05/22

D.O.I: 14/06/22

Survey held at

Bitrost Sin Ming

Des. of Damages: Fnt / Rear / O/S / H/S / W/C / Rooftop or

Rear o/s

The W/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prefl. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$ _____)

S + RS: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	839G
Vehicle Details	
Vehicle No.:	SHA9479T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Jun 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Yellow
Manufacturing Year:	2018
Engine No.:	2ZR2B88179
Chassis No.:	JTDKB3FU703078157
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	09 Jan 2019
First Registration Date:	09 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jan 2027
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	08 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$20,838.00
COE Rebate Amount:	\$14,522.00
Total Rebate Amount:	\$25,207.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Jun 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	11/06/2021 16:58 (SGT)
Date of Accident	11/06/2021 14:50 (SGT)
Exact Location of Accident	Sembawang Way, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA9479T
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-96536609
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419138
Cover Note Number	-

DRIVER

Name of Driver	CHEE KOK CHEW
NRIC No	SXXXX211F

Date Of Birth	07/02/1961
Occupation	Outdoor
Date Of Driving Pass	13/02/1990
Driving experience	31 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96536609
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 316A ANG MO KIO STREET 31 #20-307
Address complement	-
Postcode	562316
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 110621 AT ABOUT 1450HRS I WAS STOPPED VEHICLE ALONG ROAD WITH ON MY HAZARD LIGHT TO DROPPING MY PASSENGER. WHILE MY VEHICLE WAS STATIONARY, VEHICLE B COLLIDED ONTO MY REAR BUMPER. NOBODY WAS INJURED AT THE POINT OF ACCIDENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV788P
Vehicle Manufacturer	-
Vehicle Model	-

Vehicle Variant		-
Vehicle Colour		-
Vehicle Category		Private car
Name of Driver		TAN KAH WAI, JOEL
NRIC No		SXXXX729I
Contact Number		(Phone) +65-90041928
Address		-
Address complement		-
Postcode		-
Insurance Company Name		-
Nature Of Damage		-
Details of property damaged in accident		-
No. Of Passenger (Including Driver)		1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre - Personnel

Sketch Plan





Describe Circumstances of the Accident

ON 110621 AT ABOUT 1450HRS I WAS STOPPED VEHICLE ALONG ROAD WITH ON MY HAZARD LIGHT TO DROPPING MY PASSANGER. WHILE MY VEHICLE WAS STATIONARY, VEHICLE B COLLIDED ONTO MY REAR BUMPER. NOBODY WAS INJURED AT THE POINT OF ACCIDENT.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

11/6/21 - 1630H

Witnessed by Reporting Centre Personnel

Khanmarij

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 11-Jun-21

INSURANCE: MSIG

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA9479T

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TRUNK LID COVER <i>bst</i>	1	\$1,126.60	\$1,126.60
REAR TRUNK LID LOCK <i>src</i>	1	\$457.90	\$457.90
REAR TRUNK LID COVER TRIM BOARD <i>HH</i>	1	\$254.40	\$254.40
Boot Lid Trimboard, Centre <i>HH</i>	1	\$159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH) <i>HH</i>	1	\$92.50	\$ 92.50
Boot Lid Trimboard REAR <i>HH</i>	1	\$124.80	\$ 124.80
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>broken</i>	1	\$896.30	\$896.30
REAR TRUNK LID LOGO (PRIUS) <i>HCC</i>	1	\$60.80	\$60.80
REAR TRUNK LID LOGO (HYBRID) <i>HCC</i>	1	\$52.40	\$52.40
REAR TRUNK LID LOGO (TOYOTA STAR) <i>HCC</i>	1	\$52.90	\$52.90
REAR BUMPER <i>Dentel / crack</i>	1	\$458.60	\$458.60
REAR BUMPER RE-INFORCEMENT <i>bst</i>	1	\$318.80	\$318.80
REAR BUMPER LOWER COVER <i>distorted / red</i>	1	\$552.60	\$552.60
REAR BUMPER SIDE RETAINER <i>src</i>	1	\$112.70	\$112.70
REAR BUMPER TOWING COVER <i>distorted</i>	1	\$82.70	\$82.70
REAR BUMPER CLIPS <i>HCC</i>	1	\$22.00	\$22.00
REAR BUMPER SIDE CLIP <i>HH</i>	1	\$25.00	\$25.00
REAR BUMPER UPPER STOPPER (LH) <i>src</i>	1	\$76.40	\$76.40
SEAL, REAR BUMPER SIDE, LH RH <i>distorted</i>	1	\$148.40	\$148.40
REAR BUMPER UNDER SIDE COVER (LH) RH <i>HH</i>	1	\$232.00	\$232.00
ARM SUB-ASSY, REAR BUMPER, (LH) RH <i>HH</i>	1	\$139.60	\$139.60
REAR BUMPER REVERSE SENSOR <i>Dent</i>	1	\$235.70	\$235.70
TAIL LAMP ASSY (UPPER) <i>many crack RH</i>	1	\$557.90	\$557.90
TAIL LAMP ASSY (LOWER) <i>crack RH</i>	1	\$548.40	\$548.40
TAIL LAMP QUARTER PANEL <i>Dentel</i>	1	\$216.00	\$216.00
TAIL LAMP SIDE COVER <i>src</i>	1	\$256.00	\$256.00
REAR END PANEL <i>Dentel</i>	1	\$602.10	\$602.10
REAR END PANEL GARNISH <i>HH</i>	1	\$165.80	\$165.80
REAR WIRING ASSY <i>HH</i>	1	\$582.40	\$582.40
REAR SPARE TYRE PANEL <i>HH</i>	1	\$667.70	\$667.70
REAR FIBER TOOL BOX TRIM (LH) <i>HH</i>	1	\$598.00	\$598.00
REAR FIBER TOOL BOX CENTER <i>HH</i>	1	\$186.20	\$186.20
SPARE TYRE LOCK NUT <i>HH</i>	1	\$88.40	\$88.40
SPARE TYRE LOCK NUT BRACKET <i>HH</i>	1	\$113.50	\$113.50
SPARE TYRE SIDE PANEL (LH) <i>HH</i>	1	\$287.30	\$287.30
REAR EXHAUST PIPE RH <i>HH</i>	1	\$1,163.40	\$1,163.40
REAR EXHAUST PIPE HANGER <i>HH</i>	1	\$40.70	\$40.70
REAR EXHAUST PIPE INSULATOR <i>HH</i>	1	\$314.60	\$314.60
REAR FENDER, RH <i>Dentel</i>	1	\$836.70	\$836.70
REAR FENDER SHIELD (LH) <i>HH</i>	1	\$174.20	\$174.20
REAR FENDER AIR DUCT <i>distorted</i>	1	\$165.10	\$165.10

135.70 SH

SUB TOTAL					\$13,247.10
LESS 20% 35%					\$2,649.42
DISCOUNTED TOTAL					\$10,597.68
REAR TRUNK LOWER W/S MOULDING Hec	SN	1	\$180.00	\$180.00	
REAR LOWER W/S SEALANT Hec	SN	1	\$46.00	\$46.00	
REAR WINDSCREEN MOULDING Hec	SN	1	\$160.00	\$160.00	
REAR WINDSCREEN SEALANT Hec	SN	1	\$46.00	\$46.00	
REAR BUMPER ADVERTISEMENT Hec	SN	1	\$100.00	\$100.00	
REAR FENDER ADVERTISEMENT LOGO (LH) Hec	SN	1	\$100.00	\$100.00	
SUB TOTAL					\$632.00
Labour Charge					
Panel Beating		1	\$1,400.00	\$1,400.00	700/-
Spray Painting Charge		1	\$1,200.00	\$1,200.00	700/-
Wiring Charge		1	\$100.00	\$100.00	30/-
Tuff Kote		1	\$100.00	\$100.00	40/-
Towing Charge		1	\$80.00	\$80.00	40/-
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$150.00	80/-
Remove/Refix Rear Windscreen Glass		2	\$120.00	\$240.00	80/-
Remove/Refix Reverse Sensor		1	\$120.00	\$120.00	40/-
Remove/Refix Fuel Tank		1	\$80.00	\$80.00	40/-
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00	40/-
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	40/-
TOTAL LABOUR					\$4,100.00
ESTIMATE TOTAL					\$15,329.68
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

6698.30
5023.72

717.70
50/-

700/-
700/-
30/-
40/-
40/-
80/-
80/-
40/-
40/-
40/-

1670.00

14/06/2021 @ 1700hrs
NA Andrew
2/3 hrs 6 days
1 year
LKK Auto

7/12 7411.42

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: