(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/AIG21006663/Ugf3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JNR5466

at Workshop m/s Enfield

of

Insured: GAC 32875

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: JNR5466 Yr Regn: / 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Yamaha 135LC c.c 135

Colour multi colour A/C: Insured / Std / NI / NA

Sp.Reading — T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: PMYKG05S0C0027027

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Inorder / Jammed / Leaked / Burnt~~ or affected

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70-90-17 MIC

R: 90-80-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or maxxis

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	mm	L/Bal.	mm

D.O.A. 30/5/21 D.O.I. 15/6/21

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Frt & o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: ___S + RS.___SI

Photos

Others

TOTAL