

REC BY: Thuan

REF: CS3/45621006703/U43

ASSIGNMENT

8264

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 1.4/1

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBF 2884 Y Yr Regn: 21/12/2011

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha T135 c.c. 135

Colour: black/blue A/C: Insured / Std / NI / NA

Sp. Reading: 367405 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 5YP303456

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 60/100-17

R: 80/90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 19/4/21 D.O.I. 15/6/21 1630

Survey held at 21haki butik road 4

Des. of Damages (Frt) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MU: <u>1.4/1</u>
	rebate: <u>90</u>
	MU: <u>13/0</u>
	resurvey on <u>22/6/21</u>
	<u>1600</u>

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Request Form:

Emergency Form:

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Visual Insp (\$

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Prints

Others

Total

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	953A
Vehicle Details	
Vehicle No.:	FBF8264Y
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jun 2021
Vehicle Make:	YAMAHA
Vehicle Model:	T135
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	5YP303456
Chassis No.:	5YP303456
Maximum Power Output:	-
Open Market Value:	\$1,764.00
Original Registration Date:	21 Dec 2011
First Registration Date:	21 Dec 2011
Transfer Count:	1
Actual ARF Paid:	\$265.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Dec 2021
COE Category:	D - Motorcycle
COE Period (Years):	10
Q1 Paid:	\$1,902.00
COE Rebate Amount:	\$90.00
Total Rebate Amount:	\$90.00

The information contained herein is correct as at 28 Jun 2021

dp: 100/m

OK

100 x 6 = 600

600 + 800 = 1400

1400 - 90 = 1310

dp: 83/m

~~83 x 6 = 498~~

~~498 + 800 (bv) = 1298/1300~~

~~1298 - 90 = 1208~~

~~1300 - 90 = 1210~~

Bike model

Yamaha T135 Spark

Type Of Vehicle

Any

Price From

Any

Price To

Any

Class

Any

MORE SEARCH OPTIONS

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Q SEARCH

Yamaha T135 Spark (/listing/usedbike/yamaha-yamaha-t135-spark/21319/)



(/listing/usedbike/yamaha-yamaha-t135-spark/21319/)

SGD \$1500

Reg : 18/08/2011

Type: Cubs

135cc

49238km

Yamaha T135 Spark For Sale. COE Renewable. Whatsapp For Details.


Posted on : 14/06/2021

DIRECT SELLER

DETAILS (/LISTING/USEDBIKE/YAMAHA-YAMAHA-T135-SPARK/21319/)

COMPARE

Yamaha T135 Spark (/listing/usedbike/yamaha-yamaha-t135-spark/21129/)



(/listing/usedbike/yamaha-yamaha-t135-spark/21129/)

SGD\$4799

Reg : 28/02/2011

Type: Cubs

135cc

70000km

2011 Yamaha T135 Spark For Sale. Coe Non-renewable After 2026. Very Suitable For Grab Riders. No Need High Capital Investment. Mint Condition And Serviced. Great Fuel Economy And Zero Parts...

Posted on : 30/05/2021

➔ DIRECT SELLER

DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-T135-SPARK/21129/)  COMPARE

Yamaha T135 Spark (/listing/usedbike/yamaha-yamaha-t135-spark/20991/)



(/listing/usedbike/yamaha-yamaha-t135-spark/20991/)

SGD\$888

Reg : 20/05/2011

Type: Cubs

135cc

81000km

Yamaha T135 Spark For Sale, Bike In Very Good Taken Care Condition. Like New - 9/10. Engine Very Quiet. Change Engine Oil Very Regularly. Quit Riding, Changing To Car. Price Slightly Nego For...

Posted on : 17/05/2021

➔ DIRECT SELLER

DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-T135-SPARK/20991/)  COMPARE

Yamaha T135 Spark (/listing/usedbike/yamaha-yamaha-t135-spark/20144/)



(/listing/usedbike/yamaha-yamaha-t135-spark/20144/)

➔

Reg: 21/02/2011

Type: Cubs

135cc

➔

Downpayment \$500 Or \$0 Without Insurance (Terms And Conditions Apply). Pls Drop By De Xing Motor Pte Ltd For Quotation We Will Give You The Best Quote And Any Information You Need. Block 3000 Qb...

Downpayment \$500 Or Zero Down.

Posted on : 02/03/2021

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Lifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

FOR MOTORCYCLE

1. Replace (✓) 2. Repair (X) 3. Check (?)
4. Not Consistent (NC)

Vehicle No: F3F82611Y

Motorcycle

NAC	INC	Item	CON	AC	Qty
101	991886	Front Number Plate	BT	✓	
3001	995065	Front Tyre			
3002	995095	Front Rim	SCR	RR	
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	BR	✓	
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy	BT	✓	
3008	991787	Front Fork Inner Tube	NFC	✓	
3009	991789	Front Fork Outer Tube	NFC	✓	
3010	991167	Front Fork Bracket	NFC	✓	
3011	991182	Front Fork Oil Seal	NFC	✓	
3012	991174	Front Fork Garnish	NFC	✓	
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp	CRP	✓	
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing			
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror			
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp			
3021	992556	Meter Casing			
3022	992553	Meter Assy			
1112	991019	ERP Bracket			
1119	991020	ERP Unit			
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem			
3027	994427	Steering Cone			
3028	992299	Handle Bar	BT	✓	
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip	CRP	✓	
3031	995184	Handle Bar Balancer LH	dis	✓	
3032	992300	Handle Bar Balancer RH	dis	✓	
1115	992179	Fuel Tank			
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever	SCR	✓	
3035	992293	Hand Brake Lever	SCR	✓	
3036	991119	Side Fairing	SCR	✓	
3037	994220	Side Fairing Top Garnish	SCR	✓	
3038	994219	Side Fairing Inner Garnish			
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish	SCR	✓	
3042	990538	Center Fairing			
3043	993378	Rear Fairing			
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower			

NAC	INC	Item	CON	AC	Qty
1012	995074	Radiator			
1013	992738	Radiator Cowling			
3046	994146	Seat Assy			
3047	990915	Engine Crash Bar			
3048	990928	Engine Guard			
1116	990219	Battery			
1117	990224	Battery Cover			
1118	990223	Battery Bracket			
3049	991144	Foot Brake			
3050	991154	Front Foot Rest			
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber			
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest	dis	✓	
3059	993501	Rear Foot Rest Bracket	BT	✓	
3060	992581	Exhaust Muffler Heat Shield			
3061	991058	Exhaust Muffler Assy			
1115	993719	Rear LH Shock Absorber			
1115	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard			
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm			
1115	993819	Rear Sub frame			
3073	995245	Rear LH Signal Lamp			
3074	995246	Rear RH Signal Lamp			
3075	995251	Rear Taillamp			
1115	993626	Rear Number Plate			
3076	994192	Side Box			
3077	992927	Rear Box			
3078	992928	Rear Box Bracket			
3079	991328	Emblem			
1115	990247	Sticker			
		mail box		SCR	✓

No of Items: 22

Assessor: Thuvan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/06/2021 14:33 (SGT)
Date of Accident	19/04/2021 14:52 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	ALONG PIE TOWARDS CHANGI AIRPORT BEFORE TAMPINES AVENUE 5 EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBF826-XY
-----------------------------	-----------

INSURED POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	MOHAMAD HALIMI BIN HASHIM
Company Reg No	S1422953A
Email Address	jafrilulmi@gmail.com
Mobile Phone No	(Phone) +65-92285750
Alternative Phone No	+65-92285750

VEHICLE PARTICULARS

Manufacturer	Yamaha
Model	T135
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Motorcycle
Transmission	Manual
CC	134

INSURANCE COMPANY

Name of Insurance Company	FWD Singapore Pte. Ltd.
Type of Coverage	ThirdParty
Fleet Policy	No
Policy Number	PNMC2020-00005152
Cover Note Number	NA

DRIVER

Name of Driver	MOHAMAD HALIMI BIN HASHIM
----------------	---------------------------

Company Reg No	S1422953A
Date Of Birth	12/08/1960
Occupation	Outdoor
Date Of Driving Pass	26/03/1987
Driving experience	34 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-92285750
Alt. Phone Number	+95-92285750
Email Address	jstnihilmi@gmail.com
Address	Bik 68
Address complement	#12-3235
Postcode	330068
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PARTY REPORT

Name	SAADIAH BINTE SK IBRAMSAH
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Kotam Ayer Neighbourhood Police Post
Police Station Phone No.	(Phone) +65-18002969999
Alt. Police Station Phone No.	(Fax) +65-32937659
Police Station Address	Bik 72 Geylang Bahru #01-3038 Singapore 330072
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON THE 19042021 AT ABOUT 1452HRS I WAS RIDING MY MOTORCYCLE TOGETHER WITH MY WIFE WHO WAS PILLION (SAADIAH BINTE S K IBRAMSAH, 96323774) BEARING PLATE NUMBER FBF8264Y ALONG PAN ISLANG EXPRESSWAY PIE TOWARDS CHANGI AIRPORT BEFORE THE EXIT OF TAMPINES AVENUE 5, I WAS AT THE SECOND LANE AND I WAS TRAVELLING AT ABOUT 70KM/H. THERE WAS A CAR (SLS3830J) DIAGNALLY IN FRONT OF ME AND THER WAS A HEAVY TRAFFIC FORMING UP ON THE FOURTH LANE. THE CAR WANTED TO CHANGE LANE ABRUPTLY FROM THE SECOND TO THIRD LANE AS IT HAD WANTED TO MAKE AN EXIT AT THE FOURTH LANE BEFORE IT REACHED DOUBLE WHITE LINE. HOWEVER AS THE CHANGING OF LANE WAS TOO ABRUPT ANF DUE TO THE HEAVY TRAFFIC, THE CAR MADE A SUDDEN BRAKE AND STOPPED RIGHT FRONT IN FRONT OF ME. DUE TO SUDDEN BRAKE I DID NOT HAVE ENOUGH TIME TO REACT AND COLLIDED INTO THE LEFT REAR BUMPER OF THE CAR. ME AND MY PILLION RIDER FELL OFF THE MOTORCYCLE AND WAS ATTENDED BY 2 AMBULANEC AN TRAFFIC POLICE. BOTH ME AND MY PILLION RIDER WERE CONVEYED TO CHANGI GENERAL HOSPITAL AND WERE GRANTED 21 DAYS OF HOSPITALIZATION LEAVE. I WISH TO ADD THAT THE DRIVER DID NOT SIGNAL ANY INTENTION TO CHANGE LANE. ME AND MY PILLION RIDER DID NOT MANAGE TO OBTAIN ANY PARTICULARS OF THE DRIVER. I SUFFERED THE FOLLOWING INJURIES. FRACTURE ON LEFT COLLAR BONE AND ABRASSIONS ON RIGHT FOREARM, RIGHT KNEE RIGHT HAND AND FINGERS AND BOTH LEGS. MY PILLION SUFFERED A DISLOCATION ON THE SHOULDER AND ABRASSIONS ON THE RIGHT LEG.

ATTACHMENT(S)

Are accident photos available for attachment? ☐ Yes
 Was there any video captured by Car Camera? ☐ No
 Was there any audio recorded? ☐ No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLS3830J
 Vehicle Manufacturer Volkswagen
 Vehicle Model Golf
 Vehicle Variant -
 Vehicle Colour Blue
 Vehicle Category Private car
 Name of Driver NO DETAILS
 Contact Number -
 Address -
 Address complement -
 Postcode -
 Insurance Company Name AIG Asia Pacific Insurance Pte. Ltd.
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (including Driver) -

PASSENGER(S)

Name Passenger 1 (kid)
 Gender -

INJURED PERSONS DETAILS

PERSON 1:

Name of injured person MOHAMAD HALIMI
 Address -
 Address Complement -
 Post Code -
 Approximate Age Years Old -
 Injuries Sustained -
 Injured person in which vehicle? FBF8264Y
 Were seat belts worn? No
 Was this injured conveyed to hospital by ambulance? No

PERSON 2:

Name of injured person SAADIAH BINTE SK IBRAMSAH
 Address -
 Address Complement -
 Post Code -
 Approximate Age Years Old -
 Injuries Sustained -
 Injured person in which vehicle? FBF8264Y

Ver. 0042021

ACCIDENT DIAGRAM

1 FCP 27 MAY
B. 15 3:30

DRIVER

DIS/Chms:

REPORTING OFFICER
NIZAM BIN ALAN