


ASS. REQ. BY: Store 7 REPT CS/AIG 21006724 / EV13

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
at \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Sent: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Cum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMH 57886 Yr Regn: 25/3/19  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: KIA Cerato c.c. 1591  
Colour: Black A/C: Insured / Std / NI / N  
Sp. Reading: 19107 T/Radio: Insured / Std / NI / N  
Eng/No: \_\_\_\_\_  
C/No: KNAE3416:MK 592789  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Locked / Burnt or  
Brake: Inorder / Jammed / Locked / Burnt or  
Mod: NII / S/Rim / STD A/Rim or  
Tyre Size: F: 205/55R16  
R: 11  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Nexen

Front Rear  
R/Bal. S mm R/Bal. S mm  
L/Bal. S mm L/Bal. S mm  
D.O.A. 14/6/21 D.O.I. 16/6/21  
Survey held at Cycle & Carriage  
Des. of Damages: Fr / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>MV-74K</u>

Time/Date, File, Post to: ☐ : Prel. Report  
☐ : Final Report

Time/Date, File Return to:

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Inve (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



## ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /NG ZHI QIN Reg No/Reg Date SMH5788G*KC17/ 25/03/201 Date In/Mileage 15/06/2021/ 0 Chassis No KNAF3416MK5027530 Engine No G4FGJH716098 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	16/06/2021/ 08:50	QUK	282 / Kevin Leong	34720			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, SUPPORT, FRT RH DOOR, BONNET & AFFECTED AREA REPAIR ON REAR RH DOOR, BOTH FRT FENDER & BOTH FRT BODY CHASSIS					2 X 400			800 2800.00
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER , FRT RH DOOR, REAR RH DOOR & BOTH FRT CHASSIS					3 X 350			1050 2800.00
E PNT88000 TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL								120.00
M SUNDRY PERFORM RUST PREVENTION								40 120.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY SUNDRIES								20 50.00
M LAMP ASSY-HEAD, LH / CUT					1.00	1219.00	20.00	975.20
M CARRIER ASSY-FRONT END MODULE					1.00	675.00	20.00	540.00
M BEAM COMPLETE-FR BUMPER					1.00	497.00	20.00	397.60
M PANEL ASSY-FRONT DOOR, RH / DD					1.00	1277.00	20.00	1021.60
M MOULDING ASSY-FRT DR FRAME, RH / REC					1.00	37.00	20.00	29.60
M W/STRIP ASSY-FR DR BELT O/S RH					1.00	64.00	20.00	51.20
M W/STRIP ASSY-FR DR SIDE RH					1.00	102.00	20.00	81.60
M HANDLE ASSY-DOOR OUTSIDE, RH / CUT					1.00	164.00	20.00	131.20
M GUARD ASSY-FRONT WHEEL, RH / X					1.00	95.00	20.00	76.00
M ORNAMENT-KIA NO.115 / REC					1.00	32.00	20.00	25.60
M COVER-FR BUMPER / BR					1.00	633.00	20.00	506.40
M GRILLE ASSY-RADIATOR / BR					1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE					1.00	38.00	20.00	30.40
M GRILLE-FRONT BUMPER / BR					1.00	262.00	20.00	209.60
M LAMP ASSY-FRONT FOG, LH					1.00	303.00	20.00	242.40
M MOULDING-FRONT BUMPER, LH / CUT					1.00	36.00	20.00	28.80

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /NG ZHI QIN Reg No/Reg Date SMH5788G*KC17/ 25/03/201 Date In/Mileage 15/06/2021/ 0 Chassis No KNAF3416MK5027530 Engine No G4FGJH716098 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	16/06/2021/ 08:50	QUK	282 / Kevin Leong	34720			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	LAMP ASSY-SIDE REPEATER, LH	✓	100	1.00	143.00	20.00	114.40	
M	ABSORBER-FRONT BUMPER ENERGY	?	1.00	84.00	20.00	67.20		
M	AIR DUCT-FR BUMPER, LH	?	1.00	14.00	20.00	11.20		
M	STIFFNER-FR BPR LWR	?	1.00	114.00	20.00	91.20		
M	BRACKET-FR BUMPER UPR SIDE MTG	?	1.00	22.00	20.00	17.60		
M	PANEL ASSY-HOOD	X	1.00	1502.00	20.00	1201.60		
M	HINGE ASSY-HOOD, RH	X	1.00	43.00	20.00	34.40		
M	HINGE ASSY-HOOD, LH	X	1.00	43.00	20.00	34.40		

# Estimate

*Steve (LKK) OD- NM AL  
 EXCIS- ?  
 P/P  
 My BL dy  
 5 dys*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

Nett	12,221.60
7% GST on	855.51
<b>Total Payable</b>	<b>13,077.11</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	15/06/2021 18:03 (SGT)
Date of Accident	14/06/2021 18:30 (SGT)
Exact Location of Accident	Hougang Ave 3, Singapore
Additional Location Information	HOUGANG AVE 3 NEAR CHAO YING KONG TEMPLE
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH5788G
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	NG ZHI QIN
NRIC No	SXXXX755I
Email Address	ZHIQIN_85@HOTMAIL.COM
Mobile Phone No	(Phone) +65-97304366
Alternative Phone No	+65-94773274

#### VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1591

#### INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900079463-01
Cover Note Number	-

#### DRIVER

Name of Driver	NG JIA JIA
NRIC No	SXXXX625H

Date Of Birth	24/05/1986
Occupation	Indoor
Date Of Driving Pass	22/11/2008
Driving experience	12 YEARS AND 7 MONTHS
Gender	Female
Mobile Number	(Phone) +65-94773274
Alt. Phone Number	-
Email Address	JIAJIA.NG@OUTLOOK.SG
Address	BLK 663A PUNGGOL DRIVE #08-260
Address complement	-
Postcode	821663
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - U-Turn
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	Yes

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Paya Lebar Neighbourhood Police Post
Police Station Address	Blk 114 Hougang Avenue 1 #01-1270 Singapore 530114
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

##### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 11

Vehicle Registration Number	SJM3061S
Vehicle Manufacturer	Hyundai
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	Gray
Vehicle Category	Private car
Name of Driver	RUFUS
Contact Number	(Phone) +65-97982100



Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	CAR 1
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJR1331A
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	ROGER KWOK
Contact Number	(Phone) +65-81213313
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	CAR 2
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SKG8398H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	SHIRLYN
Contact Number	(Phone) +65-85113768
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	CAR 3
No. Of Passenger (Including Driver)	-

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan

Hougang Ave 3

Bus Lane



① - My car

② - SJM 3061 S

③ - SJR 1331 A

④ - SKG 8398 H

### Describe Circumstances of the Accident

On 14/06/2021 at about 1530hrs, I was at the U-turn lane along HURGING AVE 3 and intending to U-turn before turning into RAK 247 flagging compound.

I deemed the traffic was clear as the cars had stopped at the traffic light, and there was a yellow box as such I initiated a U-turn. I was slowly looking out and did not see any oncoming car. But suddenly I saw V1 SSF 3061 at the bus lane approaching forward and I could not stop in time. Thereafter, both of our vehicles collided at the same time while on the move.

My vehicle inched towards the right & front & collided into right vehicle V2 SJP 13314 & slightly on the rear of V3 SKG 834811.

We all came down to make a check, exchanged particulars & police was also at the scene. At the end, all vehicles were able to move except V1 tyre punctured. All parties informed that they were not injured at that point of time.

I wish to inform that V1 suffered damages on the right front/side & punctured tyre. V2 suffered damages on left side. V3 suffered slight damages on the rear.

### Declaration

We declare the foregoing particulars are true in every respect.



15 June 15:10pm

Policyholder's Signature / Date & Time



15:10pm 15 June

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel





**SINGAPORE  
POLICE FORCE**



T120210614/2118

Police Station Of Origin:  
Paya Lebar NPP  
114 Hougang Avenue 1 #01-1270  
SINGAPORE 530114  
Tel No: 1800-2899999

1 of 4

Report No. T120210614/2118

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 14/06/2021 21:52	Vide Report No.:	Station Diary No.: 41
--	------------------	--------------------------

Informant's Particulars			Address: APT BLK 663A PUNGGOL DRIVE #08-280 SINGAPORE 821663	
Name of Informant: NG JIA JIA			Contact No.:	Mobile: 94773274
ID Type / ID No.: NRIC NO / S9714625H			Home/Office:	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Female	Age: 35	Date of Birth: 24/05/1986	Type of Informant: Driver	Institution / School Name:
Race: Chinese			Language:	
Occupation: LOGISTIC EXECUTIVE			Driving Licence Information: Class: 3	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 14/06/2021 18:30	Type of Location: Straight Road
Location: HOUGANG AVENUE 3				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJM3061S	Car				Slightly Damaged	1
SJR1331A	Car				Slightly Damaged	3
SKG8398H	Car				Slightly Damaged	3
SMH5788G	Car				Slightly Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20210614/2118

2 of 4

Report No. T/20210614/2118

Police Station Of Origin:  
Paya Lebar NPP  
114 Hougang Avenue 1 #01-1270  
SINGAPORE 530114  
Tel No: 1800-2899999

**CONTINUATION OF REPORT**

Details of Person Involved				
Any Pedestrian Involved: No			Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL				
Driver				
Name	RUFUS		ID No.	NIL
Related Vehicle	SJM3061S (Car)		Contact No.	97982100
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	ROGER		ID No.	NIL
Related Vehicle	SJR1331A (Car)		Contact No.	81213313
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	SHIRLYN		ID No.	NIL
Related Vehicle	SKG8398H (Car)		Contact No.	85113768
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL



# SINGAPORE POLICE FORCE

Police Station Of Origin:  
Paya Lebar NPP  
114 Hougang Avenue 1 #01-1270  
SINGAPORE 530114  
Tel No: 1800-2899999



T/20210614/2118

3 of 4

Report No. T/20210614/2118

## CONTINUATION OF REPORT

Driver Name	NG JIA JIA	ID No.	S-625H
Related Vehicle	SMH5788G (Car)	Contact No.	94773274
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

### Brief Details.

On 14/06/2021 at about 1830hrs, I was at the U-turn lane along Hougang Avenue 3 and intending to U-turn before turning into Block 247 Hougang carpark. I deemed the traffic was clear as the cars had stopped at the traffic light, and there was also a yellow box as such I initiated a U-turn Suddenly, I saw V1 - SJM3061S at the bus lane approaching forward and I could not stop on time. Thereafter, both of our vehicles collided on the same time while on the move. My vehicle inched forward and collided onto the right side of V2 - SJR1331A, and slightly on the rear of V3 - SKG8398H.

We all came down to make a check, exchanged particulars and police was also at scene. At the end, all vehicles were able to move except V1 tire had punctured. All parties informed that they were not injured at that point of time.

I wish to inform that V1 suffered damages on the right front bumper and puncture tyre, V2 suffered damages on the left side, V3 suffered damages slight damages on the rear. I wish to inform that I have in-vehicle camera however yet to check on it.



**SINGAPORE  
POLICE FORCE**



T/20210614/2118

Police Station Of Origin:  
Paya Lebar NPP  
114 Hougang Avenue 1 #01-1270  
SINGAPORE 530114  
Tel No: 1800-2899999

4 of 4

Report No. T/20210614/2118

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
F /  
Sgt 3 LOW KAI TAT

Signature Of Interpreter:  
Not applicable


Officer In Charge Of Case:  
TP / GIT /  
Staff Sgt SUFIYAN BIN KHAIRI  
Contact No.: 65476390

Signature Of Informant:

Date/Time:  
14/06/2021 21:52

Classification Of Case:

Authentication Stamp  
NP168



Signature:

**Singapore Police Force**

BN 0-55

Owner or Policyholder : NG ZHI QIN  
Period of Insurance : 25 Mar 2021 To 24 Mar 2022  
Engine No. : G4FGJH716098  
Chassis No. : KNAF3416MK5027530

Vehicle No. : SMH5788G  
Policy No. : 1900079483-01  
Endorsement No. :  
Issued Date : 09 Mar 2021

#### VEHICLE COVER

Make/Model : KIA Cerato  
Engine Capacity/Tonnage : 1,591.00 CC  
Driver Restriction : NA  
Person or Classes of Persons Entitled to Drive\* :

Sum Insured : Market Value  
Off Peak Car : No

First Year of Registration : 2019  
Insuring with COE/PARF : Yes

\* Only Policyholder  
or an authorised driver who is driving on the Policyholder's order or with his/her permission  
may claim all indemnity. The Policyholder or any authorised driver only if he/she meets the specified age condition.  
You need to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 30 years old and above  
Limitation as to use\* :

Mileage Condition : Unlimited Mileage

\* This policy is for personal, domestic and pleasure purposes and for the Policyholder's business.  
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or  
business or use for any purpose in connection with Motor Trade.

Class of Use 1000cc - 1500cc

\* Limitations imposed inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport  
Amendment Act 2019, are not to be included under these headings.

Section 1  
Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$800

Section 2  
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Ng Zhi QIN - \$800 (Own Damage), \$800 (Flood Cover)

#### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65884501

2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67481000

3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800

4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 675733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or  
AIG's 82 Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

#### WEB LINKS

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that this policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of  
the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

US04822227

C&C/CP2 - GORDON

239 ALEXANDRA ROAD  
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**

This computer generated document does not require a signature.