

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

NTUL(LIS) JH
Date: 14.06.2021
Time: 10:08:29
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305473285
REGN NO : SHC1073Y
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 29.12.2016
DATE/TIME IN : 14.06.2021 09:35
ACCIDENT DATE : 10.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	ne
0002 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	1,106.00	20.00	884.80	de
0003 04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	Rp
0004 04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	Rn
0005 04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	Rn
0006 04-01-0103-0743-G	STAY-RR BUMPER RH	1	160.60	20.00	128.48	Rn
0007 04-01-0103-0852-G	REFLECTOR/REFLEX ASSY-RR	1	32.00	20.00	25.60	ant
0008 04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00	50.00	ne

1160
20% 928
SN - 50

SUB-TOTAL : 1,727.20

JOB NATURE

0000 PB PANEL BEATING
0001 SP SPRAYPAINT CHARGE
0002 17-01 CHECK ALL LIGHTING

NTUL(LIS) JH

Signature: _____ Date: _____

Acknowledged by Rep: _____

is subject to final approval from the insurance company and

Subsequent loss(es) must be reported and

No legal action shall be taken against the

Third party survey is on a "Without Prejudice" basis

Parts prices are subject to confirmation

To display damaged part(s) during survey

To reserve damaged part(s) during survey

the Repairs of the following:

NTUL(LIS) JH

100.00 250

100.00 250

50.00 250

2021
18:29

3285
73Y
000

COMFORTDELGRO ENGINEERING PTE LTD

Date: 14.06.2021

REPAIR ESTIMATE

Time: 10:08:29

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305473285
REGN NO : SHC1073Y
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 29.12.2016
DATE/TIME IN : 14.06.2021 09:3
ACCIDENT DATE : 10.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0003 L REMOVE/REFIX REVERSE SENSOR

80.00 30 560

SUB-TOTAL : 730.00

TOTAL : 2,457.20

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanpin 9749549
WP 14/6/21 CYP
C/S Resurvey after repair
- 2 days
tanpin@leantown

928
50
560
1538
4/5 \$1250
2 days

LEK Auto Consultants hereby notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: