

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |   |   |                 |       |                      |  |
|---|---|---|-----------------|-------|----------------------|--|
|   | CHINA TAIPING IN  | ISURANCE (S) PTE LTD                      |                 | Ref:  | CS3/CTI21006745/T1qc |  |
|   | 3 ANSON ROAD #<br>SPRINGLEAF TOV  | 16-00<br>VERSINGAPORE 079909              |                 | Date: | 16/06/2021           |  |
|   |   |   |                 | Code: | CTI                  |  |
| 1.  |   | Policy Particulars :- (THIRD PARTY CLAIM) |                 |       |                      |  |
|   | Insured Veh.  | XD 4071M                                  | Veh. Inspected  | d     | YM 9835J             |  |
|   | Policy No.  |   | Coverage (\$)   |       | 0.00                 |  |
|   | Claim No.   | SNM21D203233C02                           | Excess (\$)     |       | 0.00                 |  |
|   | Assign From   | CHEE SO CHOW                              | Assign Date     |       | 16/06/2021           |  |
| 2. Vehicle Particulars & Condition                                |   |   |                 |       |                      |  |
|   | Make & Model  |   | c.c             |       | 0                    |  |
|   | Engine No.  | HIDDEN                                    | Year of Reg.    |       |                      |  |
|   | Chassis No.   |   | Colour          |       |                      |  |
|   | Odometer  | -   | Steering        |       |                      |  |
|   | Brakes  |   | Modification    |       |                      |  |
|   | General   |   |                 |       |                      |  |
| 3. Conditions of Tyres  |   |   |                 |       |                      |  |
|   |   | Size                                      | Make            |       | Balance              |  |
|   | R/H Front Tyre  |   |                 |       | mm                   |  |
|   | L/H Front Tyre  |   |                 |       | mm                   |  |
|   | R/H Rear Tyre   |   |                 |       | mm                   |  |
|   | L/H Rear Tyre   |   |                 |       | mm                   |  |
| 4.  | Description of Damages  |   |                 |       |                      |  |
|   |   |   |                 |       |                      |  |
| 5.  | General Information   |   |                 |       |                      |  |
|   | Accident Date   | 07/06/2021                                | Inspection Dat  | e     | 16/06/2021           |  |
|   | Survey held at  | COSMOPOLITAN ENGRG. SER                   | VICES PTE. LTD. |       |                      |  |
|   |   | 4 LOYANG WALK<br>SINGAPORE 508787         |                 |       |                      |  |
| 5a. Remarks   |   |   |                 |       |                      |  |
|   | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |   |                 |       |                      |  |