



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21006753/Kuf3e2	
			Date: 28/06/2021	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMB 1415R	Veh. Inspected	SMA 2904U	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/06/21/1028	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	16/06/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT SCENIC (A)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	VF1RFA00659516716	Colour	METALLIC BLACK	
Odometer	173824 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/55 R20	GOODYEAR	8 mm	
L/H Front Tyre	195/55 R20	GOODYEAR	8 mm	
R/H Rear Tyre	195/55 R20	GOODYEAR	8 mm	
L/H Rear Tyre	195/55 R20	GOODYEAR	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	15/06/2021	Inspection Date	17/06/2021	
Survey held at	MUNICH AUTOCARE PTE LTD 60 JALAN LAM HUAT #07-43 CARROS CENTER SINGAPORE 737869			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	