

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD4084R

Make : HYUNDAI

Model : IONIQ(G2)

Date: 15/06/2021

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER LOWER CTR MOULDING			\$155.00
1	REAR BUMPER FOG LAMP			\$201.50
1	REAR BUMPER TOWING COVER			\$98.80
1	LICENCE LAMP			\$85.30
1	ANTENNA ASSY - SMARTK			\$40.50
1	BOOTLID			\$2,480.40
1	BOOTLID HYUNDAI PLATE			\$24.30
1	EMBLEM HYBRID			\$24.30
1	EMBLEM - IONIQ			\$31.30
	SUB TOTAL			\$4,468.85
	LESS 20%			\$893.77
	DISCOUNTED TOTAL			\$3,575.08
1	REAR BUMPER RUBBER MAT			\$50.00
1	BOOTLID COMFORT TEL NO STICKER			\$35.00
1	BOOTLID COMFORT LOGO STICKER			\$30.00
1	REAR NUMBER PLATE + TRIM COVER			\$45.00
1	BOOTLID COMFORT APP STICKER			\$30.00
1	REAR BUMPER REVERSE SENSOR			\$180.00
				\$320.00
	Labour Charge			
	PANEL BEATING			350 \$800.00
	SPRAY PAINTING CHARGE			250 \$600.00
	WIRING CHARGE			X \$50.00
	REMOVE/REFIX REVERSE SENSOR			30 \$80.00
	TOTAL LABOUR			\$1,530.00
	ESTIMATE TOTAL			\$5,425.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taughan 97493749
 WP 15/6/21 2:40pm
 P/P Resurvey after repair, new parts.
 2 days
 Taughan @ Millant.com

Date/Time: 15.06.2021 08:33

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4089055

JC NO.: 305473458

CUSTOMER

VMS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755
L (R) (O)
(P)

COUNT CARD NO.


REGN NO.: SHD4084R	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 13.06.2021 14:50
YR OF MANU 25.10.2019	TARGET DATE
CHASSIS CODE KMHC851CVLU187325	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 13.06.2021
NATURE: 3P 13.06.2021

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHD4084R YY

Vehicle No.: SHD4084R

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard