

Accident Repair Estimate

Accident Date:	<u>21/05/2021</u>
Accident Time:	<u>00:22 HRS</u>
Accident Report Number:	<u>E23642021</u>
3rd Party Claim against:	<u>SMV7627B</u>

Bus Registration Number:	<u>SMB8004Y</u>
Bus Type:	<u>MAN A24 EU5, AR, AC, 3 Axle</u>
Date of Survey:	<u>18-Jun-21</u>

Section A

[illegible]

Section B

NO.	Assessment/Repair/Spray paint (labour Cost)		
1	CONTRATOR LABOUR COST		\$ 350.00
2	WORKSHOP ADMIN COST		\$ 192.00
3	LIVERY/ADVERTISEMENT COST		NA
4	TOWING COST		NA
		Total Labour Cost	\$ 542.00

Section C

Summary		
	Total Cost	\$542.05

SURVEYOR ACCEPTANCE

NAME: RASUL - Hp 90010068
DATE: 18/06/21 @ 1120
SIGN: [Signature]

1 day
Resin after repair

SBST VERIFICATION

Nurizman Yusoff
Technical Officer
 (DID) 63754264/ (HP) 84256323 | nurizmanby@sbstransit.com.sg
Bus Engineering | Seletar Depot
3 Yio Chu Kang crescent(S786010)

NURIZMAN BIN YUSOFF
TECHNICAL OFFICER
SELETAR BUS WORKSHOP



A member of **COMFORTDELGRO**

18 JUN 2021

3P
AUTOTEAM ENGINEERING PTE LTD

7 Gambas Crescent #04-07 Singapore 757087
Tel: (65) 6253 0233 Email: sales@autoteam.com.sg
Co. Reg. No. 201205841K

bizSAFE₃



QUOTATION

Quote To

SBS Transit Ltd
Seletar Workshop
3 Yio Chu Kang Crescent
Singapore 786010

Quotation No. Q21060750
Date 14 Jun 2021
Terms Net 30

Attn: Mr Nurizman

S/No	Description	ManHour	ManHour Rate	Amount
<u>Repair Accident Bus - SMB 8004Y</u>				
1.	Supply 3 workers for 1 day work	7	S\$50.00	S\$350.00
-	Repair Right Side Headlamp Cover			
-	Spray Painting Right Side Headlamp Cover			



Remark(s) All Material To Be Supplied by SBST

Total S\$350.00

This is computer generated. No signature is required.

NURIZMAN BIN YUSOFF
TECHNICAL OFFICER
SELETAR BUS WORKSHOP

16 JUN 2021

ZEE CHEE WAH
MANAGER
SELETAR BUS WORKSHOP

TAC - ACCIDENT REPORT VIEW

90010 - YSI Page 1 of 2

RERPORT-ID : TAC019R
USER-ID : edsfof02

ACCIDENT REPORT

DATE : 24/05/2021 16:13:04
Page : 1 of 2

Company	SBS	District	SE	IP NUMBER	
Duty IO	ANDREW GOH POH LEONG	Report No.	E/2364/2021	Accident Date	21/05/2021
Report Date	24/05/2021	Shift Code	PM SHIFT	Accident Time	00:22
Place of Accident	YISHUN AVE. 2 ROAD BUS STOP (OPP. KHATIB STN)				
Road Name	YISHUN AVE. 2 ROAD	Road Name Junction	Final Cause		
Accident Type	TRAFFIC	Nature Of Accident	MINOR		
Weather Code	CLEAR	Road Surface	DRY		
Operating Hours	WORKED 10 HRS 30 MINS	Type Of Location	BUS STOP		
Traffic Volume	LIGHT	Traffic Flow	TWO WAYS		
Traffic Control	UNCONTROLLED	Ambulance Convey	N		
Collision With	VEHICLE	Type Of Collision	SIDE SWIPE - SAME DIRECTION		
Fatal	0	Serious Injury	0	Minor Injury 0	
Police Report	N	Police Report Number		Photo Taken Y	
Bus Towed	N	Sketch	Y	Mechanical Fault	N
Urgent CBR Status	N	CFMS Case	N	CFMS No	
Damage To Bus	SMB8004Y - RIGHT FRONT DMG				
Facts of Incident	I was travelling on the left most lane reaching the bus stop opp. Khatib MRT Station along Yishun Ave. 2 road when a car (SMV7627B) on my right side cut into my lane. The left front of the car side swipe the right front of my bus. No injury. That 's all.				
Brief Particulars	NA				
Reason for Late Report					

STATEMENT READ OVER TO ME
AND I AFFIRM IT TO BE TRUE AND CORRECTTHAM MENG KHUAN
Safety Officer
Selat Depot

SIGNATURE OF STAFF

NAME AND DESIGNATION OF RECORDER

TAC - ACCIDENT REPORT VIEW

Page 2 of 2

RERPORT-ID : TAC019R
USER-ID : edsfof02

ACCIDENT REPORT

DATE : 24/05/2021 16:13:04
Page : 2 of 2

Buses Involved in the Accident

1 Bus No : SMB8004Y Bus Model : MAN A24 EU5, AR, AC, 3 Axle Bus Park : SED CCTV : Y

Driver Involved in the Accident

1 Driver Category :	BC	Driver No :	90010	Svc No :	804
Gender :	MALE	Name :	Ong Yew Leng	Svc RG :	YII
SAP RG:	BOYI	NRIC :	**885B	Lic Class :	2B/3/4A
Date Join :	12/04/1997	Nationality :	Singaporean	Lic Exp Date :	31/12/2999
LSvc :	24.12	Age :	71		
Address :	Blk 861 Yishun Ave 4	#02-117		Postal Code :	760861

Third Party Details

1 Name :	FU XUAN CINDY	Race :	CHINESE	Vehicle No :	SMV7627B
NRIC :	**	Age :	20	Veh Color :	
Gender:	FEMALE	Contact No :		Veh Type :	
Veh Damage :	LEFT FRONT DMG			Veh Make :	

Witness Details

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	653M
Vehicle No.:	SMB8004Y
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jun 2021
Vehicle Make:	MAN
Vehicle Model:	NG 363F (A24)
Primary Colour:	Multicolor
Manufacturing Year:	2014
Engine No.:	50338140893815
Chassis No.:	WMAA24ZZ5E7002223
Maximum Power Output:	-
Open Market Value:	\$455,522.00
Original Registration Date:	17 Apr 2015
First Registration Date:	17 Apr 2015
Transfer Count:	1
Actual ARF Paid:	\$0.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 21 Jun 2021

OK

Multicolor

