

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref

Via Fax

Date

Your Insured

Time of Fax

Date of Acc

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

Our client has engaged us to repair the above vehicle and submit claims against the other party/partiesinvolved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- Our initial estimate of repairs of the damaged vehicle;
- Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

Tel: 6214 8355 or HP: 9824 0811 ♦ Lim Kwok Ena ♦ Jumani Bin Masudin Tel: 6214 8315 or HP: 9635 5305 ◆ Lim Tien Siong

Tel: 6214 8398 or HP: 9635 8546 Tel: 6214 8314 or HP: 9296 6006 jumanibm@cdge.com.sg Fax no. 6546 8156



If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Taxi Accident Repair



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 17.06.2021 13:38 Page: 1

JOB CARD Sales Order: 4090184 ARC Repair TP(CLSO)1 Team: JC NO.: 305473987 REGN NO.: MILEAGE **OMER** SHC1054C COMFORT TRANSPORTATION PTE LTD MAKE: 7010045 HYUNDAI E.......1/2......F OMER NO. 383 SIN MING DRIVE DATE/TIME IN 16.06.2021 20:30 RESS MODEL I - 40Singapore SINGAPORE 575717 YR OF MANU. 29.12.2016 65508755 TARGET DATE (R) (P) CHASSIS CODE COMPLETION DATE/TIME: DUNT CARD NO.

JOB DESCRIPTION


Accident Date: 16.06.2021

NATURE: 3P 16.06.2021

S/NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:		
SERVICE ADVISOR		CUSTOMER'S SIGNATURE
ledgement Slip	Exit Pass	
No.: SHC1054C JU AIG	Vehicle No.: SHC1054C	
f Service Advisor Signature/Date turned to Service Reception upon collection	Name of Service Advisor To be kept by Security Guard	Date

COMFORTDELGRO ENGINEERING PTE LTD

Date: 17.06.2021 Time: 13:46:15

REPAIR ESTIMATE

Page: 1

: 305473987 COMPANY: THIRD PARTY'S CLAIMS (CAS) JOB NO REGN NO : SHC1054C CUSTOMER: 7010045 : 0000000000 MILEAGE ADDRESS: COMFORT TRANSPORTATION PTE LTD : HYUNDAI

383 SIN MING DRIVE MAKE MODEL

SINGAPORE SINGAPORE 575717

65508755

: I-40 DATE OF REGN : 29.12.2016 DATE/TIME IN : 16.06.2021 20:30 ACCIDENT DATE : 16.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G COVER ASSY-RR BUMPER# 1 1,106.00 20.00 884.80

0002 04-01-0103-0738-G COVER-RR BUMPER LWR# 1 228.00 20.00 182.40

0003 04-01-0103-0739-G ABSORBER-RR BUMPER ENERGY 1 119.50 20.00 95.60

0004 04-01-0103-0740-G BEAM-RR BUMPER# 1 428.40 20.00 342.72

0005 04-01-0101-0111-G BUMPER COVER CLIP REAR 10 L 22.00 20.00 17.60

0006 04-01-0103-1150-A PROTECTOR MAT 1 N 50.00 2.00- 50.00

0007 04-01-0103-0851-G REFLECTOR/REFLEX ASSY-RR 1 32.00 20.00 25.60

SUB-TOTAL : 1,598.72

JOB NATURE

0000 PB	PANEL BEATING	300.00
0001 SP	SPRAYPAINT CHARGE	300.00
0002 20-05	ADVERTISMENT STICKER-BUMPER	50.00
0003 20-05	ADVERTISMENT STICKER-FENDER	200.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 17.06.2021 Time: 13:46:15

REPAIR ESTIMATE

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO : 305473987

MILEAGE

: SHC1054C : 0000000000

MAKE

: HYUNDAI

MODEL

: I-40

DATE OF REGN : 29.12.2016 DATE/TIME IN : 16.06.2021 20:3

ACCIDENT DATE : 16.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 L

REMOVE/REFIX REVERSE SENSOR

80.00

SUB-TOTAL : 930.00

AUTHORISED: YES/NO

TOTAL : 2,528.72

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE:

DATE: