

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 17.06.2021
Time: 13:46:15
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305473987
REGN NO : SHC1054C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 29.12.2016
DATE/TIME IN : 16.06.2021 20:30
ACCIDENT DATE : 16.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	1,106.00	20.00	884.80	de ✓
0002	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	pr ✓
0003	04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	X nm ✓
0004	04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	X nt ✓
0005	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	new ✓
0006	04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	new ✓
0007	04-01-0103-0851-G	REFLECTOR/REFLEX ASSY-RR ^{LH}	1	32.00	20.00	25.60	ent ✓
						SUB-TOTAL	: 1,598.72

1160
20% - 928
SN 50
978

JOB NATURE

0000	PB	PANEL BEATING	300.00	280.
0001	SP	SPRAYPAINT CHARGE	300.00	250.
0002	20-05	ADVERTISMENT STICKER-BUMPER	50.00	new ✓
0003	20-05	ADVERTISMENT STICKER-FENDER	200.00	new ✓

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 17.06.2021

Time: 13:46:15

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305473987
REGN NO : SHC1054C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 29.12.2016
DATE/TIME IN : 16.06.2021 20:3
ACCIDENT DATE : 16.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 L REMOVE/REFIX REVERSE SENSOR

80.00 30 810

SUB-TOTAL : 930.00

TOTAL : 2,528.72

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

Tanpin 27/05/21
'up' 17/6/21 @ 4pm
+ 2 days
LH Resurvey after repair
Tanpin @ Khantawon

1788
4/58/450
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: