

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/CT119012762/HCF3E2  
**Date:** 02/03/2020

**REFERENCE**

|                       |   |                      |                   |                           |
|-----------------------|---|----------------------|-------------------|---------------------------|
| Handling Insurer:     | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:           | DMCVSN14238319055 |                           |
| Claimant Vehicle No : | GBF7473S                                      | Insured Vehicle No : | GBD1148G          |                           |
| Date of Loss:         | 13/07/2019                                    | Nature of Claim:     | TP                | Claim No: SNM19D203300C02 |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |   |             |                   |
|-----------------------------|---|-------------|-------------------|
| Reg No:                     | <b>GBF7473S</b>                                 |             |                   |
| Make & Model:               | NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A) | Engine No:  | ZD30015339N       |
| Reg. Date:                  | 28/02/2017 (Man. Year: 2016)                    | Chassis No: | JN1SC2F24Z0859270 |
| Colour:                     | Gold  | Odometer:   | 0 km              |
| Engine Capacity:            | 2953 cc   |             |                   |
| Market Value/New Car Price: | N/A   |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>               |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |     |                          |     |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |                  |      |      |
|-------------------|------------------|------|------|
| Front Tyre Size:  | Rear Tyre Size:  |      |      |
| Front Left Side:  | Rear Left Side:  | 0 mm | 0 mm |
| Front Right Side: | Rear Right Side: | 0 mm | 0 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

**INSPECTION**

|                             |            |               |  |
|-----------------------------|------------|---------------|--|
| Date of Assignment:         | 13/02/2020 |               |  |
| Date Inspected:             | 22/11/2019 | Inspected At: | N-51 Automotive Pte Ltd (HQ)<br>BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB<br>Singapore 417921 |
| Estimated Period of Repair: | 0.0 days   |               |  |

**Adjuster:** LEE HOCK ANN

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 19 Feb 2020)

**Parts:** N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** LKK Auto Consultants Pte Ltd/GBF7473S/02/03/2020 19:11

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

LKK Auto Consultants Pte Ltd/GBF7473S/02/03/2020 19:11 . Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/GBF7473S/02/03/2020 19:11. Not valid without Reference section.

< END OF ESTIMATES >