

ASS. REC. BY:

Store

CS/A162100-6812/ETFS

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Cum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SL Q 7954U

Yr Regn:

24/7/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

c.c.

1591

Colour:

Blue

A/C:

Insured / Std / NI / N

Sp. Reading

91412

T/Radio:

Insured / Std / NI / N

Eng/No:

C/No:

KIA/AFX 4117/1/JS729166

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

U/Bal.

5

mm

U/Bal.

5

mm

D.O.A.

17/6/21

D.O.A.

18/6/21

Survey held at

Cycle & Carriage

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

F-1 RH b. FM LH

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-58K

Date/Time, File, Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp

(\$



: Interview

(\$



: Tech. Inve

(\$



: Wash and

(\$

TOTAL

Approved:

Date/Time/Signature



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /FONG HSIANG ENTERPRISE CO PTE L Reg No/Reg Date SLQ7954U / 24/07/201 Date In/Mileage 17/06/2021/ 0 Chassis No KNAFX411MJ5729266 Engine No G4FGGH672220 Make/Model KIA/CERATO K3 1.6 A EX BWY Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	18/06/2021/ 13:00	QUK	282 / Kevin Leong	34878

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, SUPPORT, BONNET, BOTH FRT FENDER, FRT LH DOOR & AFFECTED AREA REPAIR ON FRT RH BODY CHASSIS	6 x 350 400			3200.00 2400
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER, BOTH FRT DOOR, FRT RH BODY CHASSIS, LH A-PILLAR & LH WING MIRROR COVER	7 x 350 + 80			2530 2880.00
E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	80			120.00
M SUNDRY TO TOP UP AIRCON GAS				80.00
M SUNDRY PERFORM RUST PREVENTION				40 120.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA				40.00
A 33900099 REPLACE FRONT UNDERCARRIAGE				? 400.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				120.00
M SUNDRY TO SUPPLY BOTH FRONT SPORT RIM (f L H & RH) CAT				800.00
M SUNDRY TO TRANSFER BOTH FRT RIM INCLUDING BALACING				60.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY SUNDRIES				20 50.00
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME BT				50.00
E PNT88000				120.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /FONG HSIANG ENTERPRISE CO PTE L Reg No/Reg Date SLQ7954U / 24/07/201 Date In/Mileage 17/06/2021/ 0 Chassis No KNAFX411MJ5729266 Engine No G4FGGH672220 Make/Model KIA/CERATO K3 1.6 A EX BWY Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	18/06/2021/ 13:00	QUK	282 / Kevin Leong	34878			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
TO TRANSFER FRT LH DOOR ATTACHMENTS TO NEW PANEL					1.00	1707.00	20.00	1365.60
M	LAMP ASSY-HEAD,LH	✓ CR			1.00	1707.00	20.00	1365.60
M	LAMP ASSY-HEAD,RH	✓ BR			1.00	125.00	20.00	100.00
M	RESERVOIR & PUMP ASSY-WASHER	✓ CR			1.00	76.00	20.00	60.80
M	HORN ASSY-LOW PITCH	?			1.00	19.00	20.00	15.20
M	GUARD-AIR,RH	?			1.00	546.00	20.00	436.80
M	RADIATOR ASSY	?			1.00	623.00	20.00	498.40
M	BLOWER ASSY	?			1.00	19.00	20.00	15.20
M	GUARD-AIR,LH	?			1.00	81.00	20.00	64.80
M	COVER-ENGINE UNDER FRT	?			1.00	280.00	20.00	224.00
M	STRUT ASSY-FR,RH	?			1.00	53.00	20.00	42.40
M	BEARING-STRUT	?			1.00	72.00	20.00	57.60
M	LINK-STABILIZER	?			1.00	832.00	20.00	665.60
M	GEAR ASSY-STEERING	?			1.00	1384.00	20.00	1107.20
M	PANEL ASSY-HOOD	✓ BT			1.00	34.00	20.00	27.20
M	HINGE ASSY-HOOD,RH	✓ BT			1.00	34.00	20.00	27.20
M	HINGE ASSY-HOOD,LH	✓ BT			1.00	435.00	20.00	348.00
M	PANEL-FENDER,LH	✓ BT			1.00	435.00	20.00	348.00
M	PANEL-FENDER,RH	✓ BT			1.00	28.00	20.00	22.40
M	INSULATOR-FENDER LH	?			1.00	28.00	20.00	22.40
M	INSULATOR-FENDER RH	?			1.00	675.00	20.00	540.00
M	CARRIER ASSY-FRONT END MODULE	✓ BR			1.00	141.00	20.00	112.80
M	PAD-HOOD INSULATING	✓ CR			1.00	95.00	20.00	76.00
M	GUARD ASSY-FRONT WHEEL,RH	✓ MIS			1.00	32.00	20.00	25.60
M	ORNAMENT-KIA NO.115	✓ RC			1.00	498.00	20.00	398.40
M	MIRROR ASSY-OUTSIDE RR VIEW,LH	✓ BR			1.00	633.00	20.00	506.40
M	COVER-FR BUMPER	✓ BR			1.00	55.00	20.00	44.00
M	LIP ASSY-FRONT BUMPER	✓ CR			1.00	328.00	20.00	262.40
M	GRILLE ASSY-RADIATOR	✓ CR			1.00	54.00	20.00	43.20
M	GARNISH-RADIATOR GRILLE,UPR	✓ CR			1.00	29.00	20.00	23.20
M	STRIP ASSY-FR BUMPER UPR	?			1.00	91.00	20.00	72.80
M	MOULDING-FRONT BUMPER A/INTAKE	✓ BR			1.00	6.00	20.00	4.80
M	DUCT ASSY-AIR CURTAIN,RH	✓ MIS						

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table border="0"> <tr> <td>Cust No/Name</td><td>/FONG HSIANG ENTERPRISE CO PTE L</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLQ7954U / 24/07/201</td></tr> <tr> <td>Date In/Mileage</td><td>17/06/2021/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAFX411MJ5729266</td></tr> <tr> <td>Engine No</td><td>G4FGGH672220</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO K3 1.6 A EX BWY</td></tr> <tr> <td>Colour/Trim</td><td>B4U GRAVITY BLUE / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/FONG HSIANG ENTERPRISE CO PTE L	Reg No/Reg Date	SLQ7954U / 24/07/201	Date In/Mileage	17/06/2021/ 0	Chassis No	KNAFX411MJ5729266	Engine No	G4FGGH672220	Make/Model	KIA/CERATO K3 1.6 A EX BWY	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK
Cust No/Name	/FONG HSIANG ENTERPRISE CO PTE L														
Reg No/Reg Date	SLQ7954U / 24/07/201														
Date In/Mileage	17/06/2021/ 0														
Chassis No	KNAFX411MJ5729266														
Engine No	G4FGGH672220														
Make/Model	KIA/CERATO K3 1.6 A EX BWY														
Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	18/06/2021/ 13:00	QUK	282 / Kevin Leong	34878

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M AIR DUCT-FR BUMPER,RH / <i>MTS</i>	1.00	33.00	20.00	26.40
M LAMP ASSY-FRONT FOG,RH / <i>GR</i>	1.00	241.00	20.00	192.80
M ABSORBER-FRONT BUMPER ENERGY / <i>GR</i>	1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR	1.00	114.00	20.00	91.20
M RAIL ASSY-FR BUMPER / <i>00</i>	1.00	496.00	20.00	396.80
M BRACKET-FR BUMPER SIDE MTG,LH / <i>GR</i>	1.00	13.00	20.00	10.40
M BRACKET-FR BUMPER SIDE MTG,RH / <i>GR</i>	1.00	13.00	20.00	10.40
M PANEL ASSY-FRONT DOOR,LH / <i>00</i>	1.00	1542.00	20.00	1233.60
M W/STRIP ASSY-FR DR BELT O/S LH / <i>CUT</i>	1.00	58.00	20.00	46.40
M BLACK TAPE-FRT DOOR FRAME UPR, / <i>np</i>	1.00	13.00	20.00	10.40
M BLACK TAPE-FR DR RR,LH / <i>np</i>	1.00	12.00	20.00	9.60

Estimate

Stere CLKK)
18/6/21, 1.00pm

00 - M AL
EXCISE - ?
PIP
My Bel Sky
14 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by

7% GST on	Nett 19209.20	19,209.20 1344.64
Total Payable		20,553.84

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	18/06/2021 09:22 (SGT)
Date of Accident	17/06/2021 09:40 (SGT)
Exact Location of Accident	Ubi Rd 2, Singapore
Additional Location Information	UBI ROAD 2
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLQ7954U

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	FONG HSIANG ENTERPRISE CO PTE LTD
Company Reg No	1XXXXX458M
Email Address	NEROSERAPIS@HOTMAIL.COM
Mobile Phone No	(Phone) +65-90712588
Alternative Phone No	+65-88624880

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1700031278-02
Cover Note Number	-

DRIVER

Name of Driver	TAN JIN KIAT, GABRIEL
Passport No/FIN	SXXXX725J

Date Of Birth	31/12/1994
Occupation	Outdoor
Date Of Driving Pass	27/07/2015
Driving experience	5 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-88624880
Alt. Phone Number	-
Email Address	NEROSERAPIS@HOTMAIL.COM
Address	BLK 356B ADMIRALTY DRIVE #08-90
Address complement	-
Postcode	752356
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SHD4904A
Vehicle Manufacturer	Hyundai
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	Blue
Vehicle Category	Taxi

Name of Driver	-
Contact Number	(Phone) +65-96798778
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	XB9670L
Vehicle Manufacturer	Mitsubishi
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	TAN JIN KIAT, GABRIEL
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	MUSCLE ACHE, HEADACHE
Injured person in which vehicle?	SLQ7954U
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan




Describe Circumstances of the Accident

- Refer to police Report -


Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time



Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel



SINGAPORE POLICE FORCE



T/20210617/7023

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20210617/7023

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/06/2021 17:43		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: TAN JIN KIAT, GABRIEL			Address: 356B ADMIRALTY DRIVE #08-90 SINGAPORE 752356		
ID Type / ID No.: NRIC NO / S9445725J			Contact No.: Home/Office:		Mobile: 88624880
Nationality: SINGAPORE CITIZEN			Email: gabrieltan@chuncheng.com		
Sex: Male	Age: 26	Date of Birth: 31/12/1994	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Sales and marketing manager			Driving Licence Information: Class: 3A		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/06/2021 09:40	Type of Location: Straight Road
Location: UBI ROAD 2				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 50 Km/h
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Opposite Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SHD4904A	Car	HYUNDAI	Taxi	Blue	Seriously Damaged	0
SLQ7954U	Car	KIA	Cerato K3	Black	Seriously Damaged	0
XB9670L	Lorry	MITSUBISHI	-	White	No Damage	0



**SINGAPORE
POLICE FORCE**



T/20210617/7023

2 of 3

Report No. T/20210617/7023

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLQ7954U	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1700031278-03	24/07/2020	23/07/2021

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	TAN JIN KIAT, GABRIEL		ID No.	S9448725J
Related Vehicle	SLQ7954U (Car)		Contact No.	88624880
Hospital/Clinic	T & T FAMILY HEALTH CLINIC & SURGERY		Class of Driving Licence & Expiry	Class: 3A Date of Expiry: NIL
Date	17/06/2021		Date	17/06/2021
No. of Days granted Medical Leave		03	Degree of	Slight

Brief Details.

I was going straight along Ubi Road 2 with my Car (SLQ 7954 U) When a Comfort Taxi (SHD 4904A) made an illegal U-Turn and Bang into the right side of my vehicle which caused me to side swiped a stationary tipper truck on my left (XB 9670 L).



**SINGAPORE
POLICE FORCE**



T/20210617/7023

3 of 3

Report No. T/20210617/7023

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
NUR ADELINA BINTE MOHAMMAD FUAT
Contact No.: 65476066

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by Singpass. No signature is
required.

Date/Time:
17/06/2021 17:43

Classification Of Case:

AAA AUTO PROTECTOR PRIVATE VEHICLE
TONG HONG ENTERPRISE CO

Name of Policyholder : FONG HSIANG ENTERPRISE CO PTE LTD
Period of Insurance : 24 Jul 2019 To 23 Jul 2020
Engine No. : G4FGGH672220
Chassis No. : KNAFX411MJ5729266

Vehicle No. : SLQ7964U
Policy No. : 1700031278-02
Endorsement No. :
Issued Date : 09 Jul 2019

ABOUT THE COVER

Make/Model : KIA Cerato K3 1.6 EX

Engine Capacity/Tonnage : 1.591.00 CC

Driver Baccarat : NA

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2017

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

and indicate the location of the entrance door on the floor plan. The specified age condition

The Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

Age Condition : All Age Condition

Limitation as to Use:

(Signature)

Limitation as to Use:
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trucks.

Log# of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport

EXCESS

Section 1

Flow - 250 CFS Damages - \$5000 Trees - 50 Flood Cover - 50

Section 2

Property Damage - \$0

Windows : 5120

Hired Driver and Excess (where applicable)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS) TEL: _____

1. Contact Campaign Affiliated Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

1. Cycle & Carriage Authorized Service Centre (For all types of bicycles & all types of carriages) At:
2. Cycle & Carriage Body & Part Centre Add: 209 Pandan Gardens Singapore 625538 65664501

Body & Damage Body & Part Centre Add: 209 Fairview Gardens Singapore 159931 64278600
Body & Damage Body & Part Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278600

4. Cycle & Damage Authorised Service Centre (For accident reporting & windscreen claim only) Add. 241 Alexandra Road Singapore 119931 67461000
 5. Cycle & Damage Authorised Service Centre (For accident reporting & windscreen claim only) Add. 550 Ubi Rd S Singapore 408650 67461000

For further Approved Reporting Centres/AIG Authorised Dealers, please contact our 24-hour accident emergency hotline at +65 6358 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

17. We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1967 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1969 (Malaysia).

9500709911

CYCLE & CARRIAGE - CTEAS(KIA)

239 ALEXANDRA ROAD

SINGAPORE 159930 ANSP-MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

ALGSGMOBILEAPP