ASS. REC. BY: Tay Th REF: NS/ /N	21006831/T1vc
	SSIGNMENT
From: Date: Estimated Cost: OD (TP) / WS / TP RES / OD RES / EVA / INV / MV	Veh No: SHO 3238X Yr Regn: 2016 1 A June Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
To Inspect Vehicle No:	
at Workshop m/s	Make: Myunder 140 c.c 1685. Colour Blue A/C: Insured/Std/NI/NA
of	Sp.Reading 477606 T/Radio: Insured / Std / NI / NA
Insured: SKT 8519H	Eng/No:
Policy No.	C/No: KM H L134141 6 409/607.
Claims No. MT/1134841-002	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder/ Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or Modi: Nil / S/Rim / STD A/Rim or /
Make of Veh:	Tyre Size: F: 207/69RU6
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Est. Repairs: days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Date / Time Action / Instruction 30/6/21 LS \$2100 confirmed by email (R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Workfulle. Front Rear R/Bal. 6 mm R/Bal. 6 mm L/Bal. 6 mm L/Bal. 6 mm L/Bal. 6 mm D.O.A. 15/6/21 D.O.I. 17/6/21 Survey held at Des. of Damages: Frt / Rear / O/S / N/S / U/C / Reoftop or The U/C / Chassis frame / Body Structure affected due to collision.
Date/Time, File Pass to? : Preli. Report : Final Report Date/Time, File Return to?	Days Of Repair: 2 Resurvey No. of Trip: 1 Survey Fee: Transportation:
	i Fee: : Site Insp (\$)s+Rssi
	: Interview (\$) Photos
Reperformal: TP	: Tech. Invs (\$) Others
Lump Sum /LB.1: (* LS \$2100)	:Weelend (\$)
	TOTAL

Sheet2

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHD3238X

Make Model : HYUNDAI

: 1-40

Date: 16.06.2021

Insurance: NTUC

MVA: MS. LOKE YY

			MIVALING. EGICE 11		
Qty	Parts Description / I	abour	Туре	Unit Price	Amount
1 FRONT BUM	PER COVER				\$1,052.20
10 FRONT BUM	PER CLIPS			\$2.20	\$22.00
1 FRT BUMPER	R GRILLE RH				\$187.20
1 FRT BUMPER	R BRACKET TOP RH				\$44.80
1 RADIATOR G	RILLE				\$1,480.00
1 RADIATOR G	RILLE U MOULDING				\$94.70
1 HEADLAMP RH				\$1,800.00	
	SUB TOTAL			\$4,680.90	
		LESS 20%			\$936.18
		DISCOUNTED TOTAL		-	\$3,744.72
	V.				
					\$-
Labour Char	ge				0.0
PANEL BEAT	ING		- 1		280 \$300.00
SPRAY PAIN	TING CHARGE				250 \$300.00
WIRING CHA	RGE				× \$60.00
		TOTAL LABOUR		-	\$660.00
		ESTIMATE TOTAL			\$4,404.72
				ſ	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpon 97495409

UP 17/6/21 Rtpn

Us Nessy Spr repor

02 days

faspin ellehantorom.

Page 1



ComfortDelGro Engineering Pte Ltd

Mainline + 65 6383 6280 Facsimile + 65 6280 9755


Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 16.06.2021 16:21 Page: 1

JOB CARD Team: ARC Repair TP(CLSO)1 Sales Order: 4089760 JC NO.: 305473823 STOMER REGN NO.: MILEAGE SHD3238X COMFORT TRANSPORTATION PTE LTD MAKE: FUEL 7010045 HYUNDAI STOMER NO. E.....F 383 SIN MING DRIVE DRESS DATE/TIME IN 16.06.2021 11:40 MODEL Singapore SINGAPORE 575717 I - 4065508755 YR OF MANU 30.06.2016 .. (R) TARGET DATE (P) CHASSIS CODE COMPLETION DATE/TIME: COMPLETION DATE/TIME: COUNT CARD NO. JOB DESCRIPTION Accident Date: 15.06.2021 NATURE: 3P 15.06.2021 FRONT

LABOR CODE

DESCRIPTION



	REAR PLANTS OF THE PROPERTY OF			
CKED & PASSED OUT BY:				
ŠERVICE ADVISOR	CUSTOMER'S SIGNATURE			
vledgement Slip	Exit Pass			
No.: SHD3238X YY	Vehicle No.: SHD3238X			
of Service Advisor Signature/Date	Name of Service Advisor Date			
sturned to Service Reception upon collection	To be kept by Security Guard			

SJ04216G000M / JP Knights Pte Ltd ENTRY DATE & TIME: 16/06/2021 16:00 (SGT) SUBMITTED BY: Khin VERSION: 1 (16/06/2021 16:00 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate.

policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

16/06/2021 16:00 (SGT) 15/06/2021 18:30 (SGT) Tampines North Dr. 1, Singapore **TOWARDS BLOCK 609** Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHD3238X

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address**

Mobile Phone No Alternative Phone No

COMFORT TRANSPORATION PTE LTD

1XXXXX821R

fleetsafety@cdgtaxi.com.sg (Phone) +65-96313387 (Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission

CC

Hyundai 140

Private hire

No - Claiming third party

Taxi Auto

1685

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy Policy Number Cover Note Number AXA Insurance Pte Ltd ThirdPartyFireTheft Yes

VFX/P2419138

DRIVER

Name of Driver

NRIC No

WONG KONG SENG SXXXX741H

Accident report SJ04216G000M

Page 1 of 19

22/05/1952 Date Of Birth Outdoor Occupation 02/04/1973 Date Of Driving Pass 48 YEARS AND 2 MONTHS Driving experience Gender (Phone) +65-96313387 Mobile Number Alt. Phone Number fleetsafety@cdgtaxi.com.sg **Email Address** BLK 68 REDHILL CLOSE #30-76 Address Address complement 150068 Postcode Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Side Swipe Weather Conditions Clear Dry Road Surface OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) 3 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 UNKNOWN Name Male Gender PASSENGER 2 UNKNOWN Name Gender Female DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom?

ON 150621 AT ABOUT 1830HRS I WAS DRIVING MY VEHICLE ALONG TAMPINES NORTH DR 1 TOWARDS BLOCK 609 TO DROP MY PASSENGER. WHILE MAKING A LEFT TURN VEHICLE B WHICH ON MY RIGHT SIDE NEVER STOPPED AT STOP LINE GOING STRAIGHT AND HIT ONTO MY VEHICLE. NOBODY WAS INJURED AT THE POINT OF ACCIDENT.

ATTACHMENT(S)

CIRCUMSTANCES OF ACCIDENT

Are accident photos available for attachment? Was there any video captured by Car Camera? Reasons for not uploading a video of the accident Was there any audio recorded?

Yes

Yes

FILE IS NOT SUITABLE

No

DETAILS OF OTHER VEHICLE PROPERTY 1



Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Name of Driver NRIC No Contact Number Address Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident No. Of Passenger (Including Driver)

SKT8519H

Kia

Private car CHAN EE FONG, LOUIS SXXXX424G

(Phone) +65-96875836

3

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act(PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my w orkshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could invoive disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time / 6 / 6 / 2 0 2 1 - 12 (SH 16).

Sketch Plan

Policyholder's Signature (If driver is not the policyholder) / Date & Time / 6 / 6 / 2 0 2 1 - 12 (SH 16).

Witnessed by Reporting Centre Personnel Washers

Describe Circumstances of the Accident

ON 150621 AT ABOUT 1830HRS I WAS DRIVING MY VEHICLE ALONG TAMPINES NORTH DR 1 TOWARDS BLOCK 609 TO DROPP MY PASSANGER. WHILE MAKING A LEFT TURN VEHICLE B WHICH ON MY RIGHT SIDE NEVER STOPPED AT STOP LINE GOING STRAIGHT AND HIT ONTO MY VEHICLE. NOBODY WAS INJURED AT THE POINT OF ACCIDENT.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time / G / G / J D A | - I \ I F A

Witnessed by Reporting Centre



