

305473981 Our Job Ref No 3 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 Date 21/06/21 **FINALIZATION FORM** LKK Fax: **TAUFIKH** Attn : SHD3719A 16/06/21 Vehicle Reg No. Date of Accident: The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-**NTUC SLC2155R** The repair job shall bill to: 1. 2. The finalized amount shall be: Spare Parts after List discount (a) (b) Labour Charges **Total for Part-By-Part Repair Cost** (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% \$1,850.00 Final Lumpsum Repair cost 3. Estimated normal period for repairs: 2 working days. 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days Thank you for your assistance. We confirm the estimates and 5. finalized amount Signature : Signature: JUMANI Name Name 25/6/21 Tel : 62148315 Date 65468156 Fax For Official Use Only Document Confirm By Item Amount Attached Remarks (Signature) Yes or No YES Rental Rate P/Day 2. Loss of Income Paid NO 3. Survey Fees LTA Search Fee \$7.49 / \$2.00 5. Medical Fees (on behalf of driver, if applicable) Overrun

Remarks: