

Our Job Ref No : 305474308

Date 23/06/21

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. SHC3578U

Date of Accident : 18/06/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG — SMX6606H
2. The finalized amount shall be:

(a) Spare Parts after List discount	<u>\$976.12</u>
(b) Labour Charges	<u>\$630.00</u>
<b>Total for Part-By-Part Repair Cost</b>	<u>\$1,606.12</u>
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	<u>                    </u>
<b>Final Lumpsum Repair cost</b>	<u>                    </u>

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : 

Name : NAZ LKK

Date : 8/7/2021

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 23.06.2021  
Time: 15:00:41  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305474308  
REGN NO : SHC3578U  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 24.07.2019  
DATE/TIME IN : 18.06.2021 12:15  
ACCIDENT DATE : 18.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G COVER-RR BUMPER#	1	459.40	20.00	367.52
0002 04-01-0101-0111-G BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0003 04-01-0104-2533-G MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0004 09-01-9999-0068-A REVERSE SENSOR ASSY*	1 N	180.00	2.00-	180.00
0005 04-01-0104-1150-A PROTECTOR MAT	1 N	50.00	0.20	50.00
SUB-TOTAL :				976.12

JOB NATURE

0000 PB	PANEL BEATING (SHC3578U)	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00
SUB-TOTAL :		630.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 23.06.2021

Time: 15:00:41

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305474308  
REGN NO : SHC3578U  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 24.07.2019  
DATE/TIME IN : 18.06.2021 12:1  
ACCIDENT DATE : 18.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,606.12

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHC3578U DOA: 18.06.21

Make : HYUNDAI

Model : IONIQ

Date: 21/6/21

Insurance: AIG ILKK

MVA: JUMANI

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR BUMPER ASSY			\$459.40	CRK
1	REAR BUMPER CLIP			\$22.00	NEC
1	REAR BUMPER CENTRE MLDG			\$451.25	DEF
1	REAR BUMPER BEAM			\$394.80	XSVC
SUB TOTAL				\$1,327.45	
LESS 20%				\$265.49	
DISCOUNTED TOTAL				\$1,061.96	
	REVERSE SENSOR			\$180.00	DEF
	REAR BUMPER MAT			\$50.00	NEC
				\$130.00	
	Labour Charge			\$400.00	350
	PANEL BEATING			\$300.00	250
	SPRAYPAINT			\$80.00	30
	REMOVE/REFIX REVERSE SENSOR				
TOTAL LABOUR				\$780.00	
ESTIMATE TOTAL				\$1,971.96	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be

NA ~ LKK  
21/6/2021 1605  
PIP  
2 DAYS  
CHECK ITEM PHOTOS  
BEFORE PAINT PHOTOS

- Instructions to be followed by the Repairer of the following:
- To resurvey before after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: