

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Ave 2, #01-17
Singapore 417921
Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

Our Ref: **SMD 9485 A**
Your ref: **SFU 6885 S**

21 June 2021

AUTO & GENERAL INSURANCE (S) PTE LTD
SINGAPORE SHOPPING CENTRE
190 CLEMENCEAU AVENUE #03-01
SINGAPORE 239924
Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : WONG KAI CHONG
VEHICLE NUMBER : SMD 9485 A
YOUR INSURED VEHICLE NUMBER : SFU 6885 S
ACCIDENT ON 18 June 2021 ALONG NER BRIDGE RD JUNC UPP CROSS ST
AT ABOUT 14:15 HOURS

We refer to your email / fax dated **21 June 2021** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK Auto Consultants Pte Ltd** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD
Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-17
Singapore 417921
6842 0051 / 6744 0510 (Melody)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



.....
Twincar Automotive Pte Ltd

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!
Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection: