

KIM HOE TYRE & BATTERY
KAKI BUKIT AUTOHUB
01-10 SINGAPORE 417921
TEL:67472427

Customer

Vehicle Ident no.

Repair order no.
R001950

Technician

License plate no.
SMC3179D

First reg. date

Model

Toyota : C-HR : ZGX10 (10/2016-)

Complaints or reason for alignment check

			Before	Target Data	Actual
Rear axle	Camber	left		-0°43' +/-0°45'	-1°21'
		right			-1°35' *
		cross		0°00' +/-0°45'	0°13'
	Toe	left		0°05' +/-0°03'	-0°01' *
		right			0°06'
		total		0°10' +/-0°10'	0°05'
Geometrical driving axis			0°00'	-0°04'	
Front axle	Camber	left		0°06' +/-0°45'	-0°24'
		right			-0°17'
		cross		0°00' +/-0°45'	-0°07'
	Caster	left		6°36' +/-0°45'	6°33'
		right			6°35'
		cross		0°00' +/-0°45'	-0°02'
	SAI	left		13°49'	14°21'
		right			15°02'
		cross		0°00'	-0°41'
	Track differential angle	left			
		right			
	Toe	left		0°03' +/-0°03'	-0°11' *
		right			0°03'
		total		0°06' +/-0°10'	-0°08' *
	Setback			0°00'	
Max steering lock	left steer	left		-39°30' +/-2°00'	
		right		33°50' +/-2°00'	
	right steer	left		33°50' +/-2°00'	
		right		-39°30' +/-2°00'	

* This value is not within specification. Tire wear, handling and safety problems may result.