

A&S, REC. BY:

Steve

CS/AIG 21006884/EFV 3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD-RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

SIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Cum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: _____

SMP 240K

Yr Regn: _____

6/9/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Mitsubishi Attrage

c.c. 1193

Colour: _____

Silver

A/C: Insured / Std / NI / N

Sp. Reading _____

39941

T/Radio: Insured / Std / NI / N

Eng/No: _____

C/No: _____

MMRSTA 13-APR 002008

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bridgestone

Front

Rear

R/Bal. _____

5

mm

R/Bal. _____

5

mm

L/Bal. _____

5

mm

U/Bal. _____

5

mm

D.O.A. _____

21/6/21

D.O.I. _____

22/6/21

Survey held at _____

cycle & collage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt RH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

22/6/2021 @ 2.15pm Revert to AIG via Merimen

Date/Time, File, Pass to?

☐

Prell. Report

☐

Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Inve (\$ _____)

☐

Weekend (\$ _____)

Approved:

Date/Time, File, Pass to?



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
FOO MEI LIN ROSELINE MRS.KONG MEI LIN ROSELINE 8 ELLIOT WALK SINGAPORE 458663 Contact No	Cust No/Name KCV12020/FOO MEI LIN ROSELINE MRS.KONG M Reg No/Reg Date SMP240K*DC17P/ 06/09/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH002668 Engine No 3A92UHX8994 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV12020	CRDVCH	21/06/2021/ 17:35	BLC	442 / CocoLu	12306

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW BONNET, FRT BUMPER, FRT FENDER RH, FRT SUPPORT PANEL 4 x 457				1800.00
REPAIR FRT DOOR RH,				1750.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH, FRT DOOR RH 5 x 357				100.00
FRT SUPPORT PANEL				50.00
E PNT88000 REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR (photo)				30.00
M SUNDRY FRT NUMBER PLATE WITH FRAME - BR				120.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				40.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				20.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				80.00
M SUNDRY Sundry				
A 54900099 CHASSIS ELECTRICAL FREE TEXT (Top up A/c gas) (photo)				
M FACE,FR BUMPER - BR	1.00	706.00	00.00	706.00
M COVER,HEADLAMP SUPT PANEL - CUT	1.00	62.00	00.00	62.00
M BRACKET,FR BUMPER,RH - BR	1.00	13.00	00.00	13.00
M GARNISH,FR BUMPER,RH - ?	1.00	127.00	00.00	127.00
M AIR DAM,SIDE,FR RH - BR	1.00	18.00	00.00	18.00
M MARK,THREE-DIA - APC	1.00	70.00	00.00	70.00
M GRILLE,RADIATOR - CUT	1.00	557.00	00.00	557.00
M GRILLE,FR UNDER - BR	1.00	165.00	00.00	165.00
M COVER,FR BUMPER - ?	1.00	12.00	00.00	12.00
M HOOD - D/H	1.00	737.00	00.00	737.00
M HINGE,HOOD,LH - ?	1.00	56.00	00.00	56.00
M HINGE,HOOD,RH - ?	1.00	56.00	00.00	56.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
FOO MEI LIN ROSELINE MRS.KONG MEI LIN ROSELINE 8 ELLIOT WALK SINGAPORE 458663 Contact No	Cust No/Name KCV12020/FOO MEI LIN ROSELINE MRS.KONG M Reg No/Reg Date SMP240K*DC17P/ 06/09/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH002668 Engine No 3A92UHX8994 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV12020	CRDVCH	21/06/2021/ 17:35	BLC	442 / CocoLu	12306			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M LATCH, HOOD	X				1.00	69.00	00.00	69.00
M FENDER, FR RH	00				1.00	500.00	00.00	500.00
M SHIELD, FR WHEELHOUSE, RH	?				1.00	98.00	00.00	98.00
M PANEL ASSY, FR END	00				1.00	1055.00	00.00	1055.00
M PANEL, HEADLAMP SUPPORT, UPR	?				1.00	66.00	00.00	66.00
M GARNISH, FR FENDER	BR				1.00	65.00	00.00	65.00
M GARNISH, FR PILLAR, RH	BR				1.00	30.00	00.00	30.00
M HEADLAMP ASSY, RH	BR				1.00	663.00	00.00	663.00
M HEADLAMP ASSY, LH	?				1.00	663.00	00.00	663.00
M LAMP ASSY, FOG, FR LH	?				1.00	305.00	00.00	305.00
M MOTOR, WINDSHIELD WASHER	?				1.00	30.00	00.00	30.00
M TANK, WINDSHIELD WASHER	?				1.00	75.00	00.00	75.00
M CONDENSER ASSY, A/C REFRIGE	?				1.00	762.00	00.00	762.00
M HOSE, A/C COMPR SUCTION	?				1.00	231.00	00.00	231.00
M PIPE, A/C CONDENSER OUTLET	?				1.00	305.00	00.00	305.00
M PANEL, AIR GUIDE	BR				1.00	112.00	00.00	112.00
M RADIATOR ASSY	?				1.00	972.00	00.00	972.00

Estimate

22/6/21, 12.9pm

Sterck (LKK)

00- NM AL

EXPRS -?

P/P

My Bel sy

8 Lys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Estimate

Sterk (CLKK) 00- Not AL
 22/6/21, 12.9pm EXPRS -?
 P/P
 My Bel Sy
 8 d/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- Any modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

Authorized signatory and company stamp

Nett	12,570.00
7% GST on	12570.00
Total Payable	13,449.90

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/06/2021 09:15 (SGT)
Date of Accident	21/06/2021 15:30 (SGT)
Exact Location of Accident	907 E Coast Rd, Singapore 459107
Additional Location Information	THE U-TURN ON EAST COAST ROAD/CROSS-ROAD SECTION
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMP240K
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	FOO MEI LIN ROSELINE MRS.KONG MEI LIN ROSELINE
NRIC No	SXXXX999I
Email Address	ROCKERULER888@GMAIL.COM
Mobile Phone No	(Phone) +65-90681923
Alternative Phone No	+65-93822426

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1193

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900157279
Cover Note Number	-

DRIVER

Name of Driver	KONG SUI KHIAN RICHARD
NRIC No	SXXXX554J

Date Of Birth
Occupation
Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

22/04/1954
Indoor
05/03/1975
46 YEARS AND 3 MONTHS
Male
(Phone) +65-93822426
-
ROCKERULER888@GMAIL.COM
8 ELLIOT WALK
-
458663
No
Spouse
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - U-Turn
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

No
2
No
-
Yes
1
No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No
No
-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
No
No

DETAILS OF OTHER VEHICLE PROPERTY: 11

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement

SKS8102G
Honda
Vezel
-
White
Private car
WONG YEW HOONG
(Phone) +65-96721131
-
-

Vehicle Code
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

At about 1525/1530 Hours on 21/06/2021, I was exiting Esso Petrol Station at East Coast Road heading towards Upper East Coast Road and immediately executing an U-turn (permissible) at the cross-road/junction of East Coast Road and Still Road/Still Road South. There was one car ahead of me which executed the U-turn first and I immediately followed him. Unfortunately there was a fast on-coming car in the opposite direction heading straight on along East Coast Road just as I was almost completing my U-turn. As such the front of my car collided into the front door (driver's side) of veh no. SKS8102G, as shown in the diagram. I believe SKS8102G had the right of way as the traffic lights were green in his favour and he was going straight on along East Coast Road.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

21/06/2021 1715.

CERTIFICATE OF INSURANCE

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Policyholder : FOO MEI LIN ROSELINE MRS KONG MEI LIN ROSELINE
Period of Insurance : 06 Sep 2019 To 05 Sep 2021
Engine No. : 3A92UHX8994
Chassis No. : MMBSTA13AKH002668
Vehicle No. : SMP240K
Policy No. : 1900157279
Endorsement No. :
Issued Date : 16 Sep 2019

ABOUT THE COVER

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT
Engine Capacity/Tonnage : 1,193.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2019
Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

FOO MEI LIN ROSELINE MRS.KONG MEI LIN ROSELINE - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
4. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504620217

C&CMICP2 - ANNAL

239 ALEXANDRA ROAD

SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. J. J. J.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

BBONMO