

ASS. REC. BY:

REF:

AGT/ 21006886144

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

03/26

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKV 632E

Yr Regn:

04 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Lexus

RX 450h.c.c

3456

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

222964

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JT TBC11 A10 2042157

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

mic

235/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

5

mm

L/Bal.

9

mm

L/Bal.

5

mm

D.O.A.

18/5/21

D.O.I.

22/6/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M/s : Auto & General Insurance (Singapore) Pte Ltd
190, Clemenceau Avenue, #03-01,
Singapore Shopping Centre,
Singapore 239924

Estimate bill : TT 23 / 21 / TP / WT

Attn : Motor Claims Department
Tel : 6221 2111
Fax : 6725 0611

Registration No : SKV632E
Make model : Toyota Lexus RX450
Hybrid

Mileage : Date : 29 / 05 / 2021

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SLM4384E AND SKV632E
ALONG BLK 506B, SERANGOON NORTH AVEVUE 4 CARPARK ON 18 MAY 2021 AT ABOUT 1340HRS.

1pc	Front LH fender	\$	945.00	✓
1pc	Front LH rim	\$	2,398.00	X
1pc	Front LH door	\$	1,538.00	X
1pc	Front LH door protector with chrome moulding	\$	365.00	✓
1pc	rear LH door	\$	1,484.00	X
1pc	rear LH door protector with chrome moulding	\$	257.00	✓
1pc	LH door side skirt	\$	648.00	X
	rear LH fender	\$	1,349.00	X
	rear LH rim	\$	2,398.00	✓
	rear bumper	\$	783.00	X
	Sub A total :	\$	12,165.00	
	Less 10% discount :	\$	1,216.50	
	A total :	\$	10,948.50	
	Remove & refit front LH fender, LH door side skirt	\$	300.00	X
	Remove and refit front LH wheel, rear LH wheel	\$	100.00	200
	Balancing front LH wheel, balancing rear LH wheel			
	Total amount of Page 1 :	\$	11,348.50	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

/s : Auto & General Insurance (Singapore) Pte Ltd
190, Clemenceau Avenue, #03-01,
Singapore Shopping Centre,
Singapore 239924

Estimate bill : TT 23 / 21 / TP / WT

Registration No : SKV632E

Motor Claims Department
6221 2111
6725 0611

Make model : Toyota Lexus RX450
Hybrid

Mileage : Date : 29 / 05 / 2021


TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SLM4384E AND SKV632E
LONG BLK 506B, SERANGOON NORTH AEVNU 4 CARPARK ON 18 MAY 2021 AT ABOUT 1340HRS.

Remove and transfer front LH door necessary attachment spare part items	
Remove and refit front LH door, front LH door protector,	\$ <i>na</i> 300.00 X
Remove and transfer rear LH door necessary attachment spare part items	
Remove and refit rear LH door, rear LH door protector	\$ <i>na</i> 600.00 X
Remove and refit rear windscreen	
Heat / weld / cut / renew rear LH fender, heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment Jack	\$ 500.00 <i>400</i>
Remove and transfer rear bumper necessary attachment spare part items	
Remove and refit rear bumper	\$ <i>na</i> 200.00 X
Under coating on LH damaged portion.	\$ <i>na</i> 150.00 X
Putty / primer application, spray painting front LH fender, front LH door, rear LH door, rear LH fender, rear bumper (Pearl White)	\$ 700.00 <i>600</i>
Balance brought forward from Page 1 :	\$ 11,348.50
Grand final amount :	\$ 13,798.50

Grand final amount :

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/05/2021 15:00 (SGT)
Date of Accident	18/05/2021 13:40 (SGT)
Exact Location of Accident	Serangoon, Singapore
Additional Location Information	BLK 506B SERANGOON NORTH AVE 4 CARPARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV632E
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	ANG WEI CHONG (HONG WEICONG)
NRIC No	SXXXX878Z
Email Address	ray@hooover-melamine.com
Mobile Phone No	(Phone) +65-97894787
Alternative Phone No	+65-97270060

VEHICLE PARTICULARS

Manufacturer	Lexus
Model	Rx450h
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	3500

INSURANCE COMPANY


Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5079173448-05
Cover Note Number	5079173448-05

DRIVER

Name of Driver	CHONG EE PING(ZHANG YINPING)
NRIC No	SXXXX057C

Accident report SS1Q215J0001

Page 1 of 11



A: SKV632E
B: SLM4384E

Carpark Bk 506B Serangoon North Ave 4

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18 May 2021 at & around 1340hrs, I was driving at the carpark near Bk 506B Serangoon North Ave 4. My vehicle was moving straight when suddenly a Honda came out of the parking lot and hit my vehicle's LH side. After that the Honda immediately moved back into the parking lot.

☐ Claim OD/TP at Su Brothers ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop: Tropical Success Auto Care

Email address: tsac303@singnet.com.sg

& myself

Email address:

Note: Please take note that your insurer have 14 days timeframe for you to submit your damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true to every respect.

Signature of the insured

Date

Signature

Date

Signature of the insurer's representative

Date