



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21006886/Ktf3n2 Date: 02/11/2021 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLM 4384E	Veh. Inspected	SKV 632E
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10010294/ST	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	22/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	LEXUS RX450H (A)	c.c	3456
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	JTJBC11A102042157	Colour	METALLIC PEARL WHITE
	Odometer	222964 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/60 R18	YOKOHAMA	9 mm
	L/H Front Tyre	235/60 R18	YOKOHAMA	9 mm
	R/H Rear Tyre	235/60 R18	MICHELIN	5 mm
	L/H Rear Tyre	235/60 R18	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/05/2021	Inspection Date	22/06/2021
	Survey held at	TROPICAL SUCCESS AUTO CARE BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	