



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2202123

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 13/04/2022  
Reference CC6/CTI21006890/Uga3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 1648Z  
Insured Veh. SMJ 3275Y  
Claim No. SNM20D200972  
Policy No. DMPCSN3018621900  
Accident Date 21/02/2020  
Inspection Date 22/06/2021

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (7%)</b>                | <b>28.00</b>  |
| <b>Grand Total</b>             | <b>428.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                                  |                 |                                                              |  |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|-----------------|--------------------------------------------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                         |                                                                                                                  |                 | Ref: CC6/CTI21006890/Uga3q2<br>Date: 13/04/2022<br>Code: CTI |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                                  |                 |                                                              |  |
| Insured Veh.                                                                                                                           | SMJ 3275Y                                                                                                        | Veh. Inspected  | GBJ 1648Z                                                    |  |
| Policy No.                                                                                                                             | DMPCSN3018621900                                                                                                 | Coverage (\$)   | 0.00                                                         |  |
| Claim No.                                                                                                                              | SNM20D200972                                                                                                     | Excess (\$)     | 0.00                                                         |  |
| Assign From                                                                                                                            |                                                                                                                  | Assign Date     | 22/06/2021                                                   |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                                  |                 |                                                              |  |
| Make & Model                                                                                                                           | mitsubishi canter fea01 (A)                                                                                      | c.c             | 2998                                                         |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                                           | Year of Reg.    | 2019                                                         |  |
| Chassis No.                                                                                                                            | FEA01BA30034                                                                                                     | Colour          | WHITE                                                        |  |
| Odometer                                                                                                                               | 68441 KM                                                                                                         | Steering        | IN ORDER                                                     |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                                         | Modification    | NIL                                                          |  |
| General                                                                                                                                | GOOD                                                                                                             |                 |                                                              |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                                  |                 |                                                              |  |
|                                                                                                                                        | Size                                                                                                             | Make            | Balance                                                      |  |
| R/H Front Tyre                                                                                                                         | 195 R15                                                                                                          | AUSTONE         | 6 mm                                                         |  |
| L/H Front Tyre                                                                                                                         | 195 R15                                                                                                          | AUSTONE         | 6 mm                                                         |  |
| R/H Rear Tyre                                                                                                                          | 195 R15 (D)                                                                                                      | AUSTONE         | 6/6 mm                                                       |  |
| L/H Rear Tyre                                                                                                                          | 195 R15 (D)                                                                                                      | AUSTONE         | 6/6 mm                                                       |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                                  |                 |                                                              |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                                                                  |                 |                                                              |  |
| <b>5. General Information</b>                                                                                                          |                                                                                                                  |                 |                                                              |  |
| Accident Date                                                                                                                          | 21/02/2020                                                                                                       | Inspection Date | 22/06/2021                                                   |  |
| Survey held at                                                                                                                         | LIU'S BROTHER AUTO ENGINEERING WORKSHOP<br>1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |                 |                                                              |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                                  |                 |                                                              |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                                  |                 |                                                              |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                                                  |                 |                                                              |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                                  |                 | 2 Working Days                                               |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 1648Z

| Qty                                | Description of Parts                                                            | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
| 1                                  | <b><u>REPLACEMENT OF PARTS</u></b>                                              | CRACKED   | 248.20                    | 248.20            |
|                                    | REAR LH TAILLAMP                                                                |           | -                         | -62.05            |
|                                    | LESS 25% DISCOUNT                                                               |           | 248.20                    | 186.15            |
|                                    | <b><u>SPECIAL NETT ITEMS</u></b>                                                | BENT      |                           |                   |
|                                    | REAR LH NUMBER PLATE (METAL) (SN)                                               |           | 28.00                     | 14.00             |
|                                    |                                                                                 |           | 28.00                     | 14.00             |
|                                    | <b><u>LABOUR</u></b>                                                            |           |                           |                   |
|                                    | TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION .                |           | 30.00                     | 20.00             |
|                                    | LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS.          |           | 300.00                    | 200.00            |
|                                    | TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA. |           | 500.00                    | 200.00            |
|                                    |                                                                                 |           | 830.00                    | 420.00            |
| <b>GRAND TOTAL</b>                 |                                                                                 |           | <b>1,106.20</b>           | <b>620.15</b>     |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                                                 |           |                           | <b>620.15</b>     |

Report Ref No. CC6/CTI21006890/Uga3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. GBJ 1648Z

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. GBJ 1648Z

### RE-INSPECTION

