

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	198R GST Reg. No. 19	9-96071	198-R	
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	ef:	CS/AGI21006913/Auf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	22/11/2021	
			С	ode:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJK 738D	Veh. Inspected		SLV 6191J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10010612/CD	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		22/06/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	RU11230840	Colour		BLUE	
	Odometer	29064 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	DUNLOP		6 mm	
	L/H Front Tyre	215/60 R16	DUNLOP		6 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP		6 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	19/06/2021	Inspection Date		24/06/2021	
	Survey held at CARWAY ENTERPRISE					
		53 UBI AVENUE 1 #03-01 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934				
5a.	. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	D)III ACCORDANC	Estimate Days of Repair				
Edilliato Dayo of Ropali						

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: