



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KHONG LYNN			Ref: CS/ASM21006918/T1tce2 Date: 23/11/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLP 6489H	Veh. Inspected	SKC 4152Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	S1M03C7I	Excess (\$)	0.00	
Assign From	KHONG LYNN	Assign Date	22/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA 1.6	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KMHDH41CMCU237567	Colour	WHITE	
Odometer	143114 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	FALKEN	6 mm	
L/H Front Tyre	215/45 R17	FALKEN	6 mm	
R/H Rear Tyre	215/45 R17	FALKEN	6 mm	
L/H Rear Tyre	215/45 R17	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY, FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/06/2021	Inspection Date	23/06/2021	
Survey held at	SYNERGY BUILDING KAKI BUKIT #01-44			
Repairer	TSL AUTO GARAGE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	