

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 23.06.2021

Time: 13:59:38

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305474267
REGN NO : SHC7623X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 18.06.2021 09:55
ACCIDENT DATE : 17.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 03-01-0104-2137-G CAP ASSY-WHEEL HUB

189.50 151.60
1 186.90 20.00 149.52

SUB-TOTAL : 149.52

JOB NATURE

0000 PB PANEL BEATING

350.00

0001 SP SPRAYPAINT CHARGE

250.00

SUB-TOTAL : 600.00

TOTAL : 749.52 751.60

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

NA2 LKK
21/6 from 1555
PIP
1 20 days
AFTER REPAIR PHOTOS