



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 21/06/2021

User ID : JeongCH

Section A - Accident Details

Registration Number	SMB290P
Case Reference Number	BUS/06/21/5020
Registration Date	6/20/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Leow Yoon Chin
Type of Accident	Head On
Accident Date and Time	6/15/2021 1:50 AM
Accident Reported Date and Time	6/15/2021 4:45 AM
Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB290P-FRONT PORTION SJH3783T (TP) INSURED WITH CHINA TAIPING
Prepared Date and Time	6/19/2021 9:56 AM
Chassis Number	WMAA22ZZ3C7001363
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$956.00	\$0.00
Total Spare Part Cost	\$5,357.67	\$0.00
Total Other Cost	\$200.00	\$0.00
TOTAL COST	\$8,633.67	\$0.00
Temp Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	19/06/2021 10:35 AM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/06/2021

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, If applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,120.00 <i>CSB x3</i>	<i>1590</i>
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, If applicable
TO PUTTY & RESPRAY	\$956.00	<i>786</i>
Total Spray Painting & Panel Beating	\$956.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, If applicable
OWING CHARGE	\$200.00	<i>receipt? 200 /</i>
Total Other Costs	\$200.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
010152	Body	F01001-CW266	COVER, HEADLAMP: FRT, RH, FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	<i>CR</i>
010305	VE	81.25101-6540	HEADLAMP, RH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	<i>CR</i>
010307	VE	81.25320-6112	FLASHER, AUX HEADLAMP, RH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	<i>CR</i>
010154	Body	F01001-CW263	FLAP, FRONT: FOR MAN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	<i>CR</i>
010151	Body	F01001-CE265	BUMPER, FRONT: CENTRE, FOR MAN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	<i>CR</i>
			FRONT NUMBER PLATE	1.00	\$75.00	0.00	\$75.00		<i>BT</i>
			SMRT STICKER	1.00	\$75.00	0.00	\$75.00		<i>CR</i>
009375			RATAINER MALE & FEMALE	1.00	\$54.24	10.00	\$48.82		<i>CR</i>
Total					\$7,424.54		\$6,697.09		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resur
48 200/0068
4 days
45
21/06/21 @ 1425
Resur after repv
SMB 2808