

REPAIR ESTIMATE*

20/06/21

1600

ef

MAKE :

MODEL **IONIQ G3**

CHIANG/CHINA

MODEL	IONIQ G3	CHANG/CHINA		
Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER STAY LH /RH		\$138.10	\$276.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
2	BUMPER LICENCE LAMP LH/RH		\$85.30	\$170.60
1	BUMPER FOG LAMP			\$201.50
1	BOOTLID EMBLEM HYBRID			\$24.30
1	BOOTLID EMBLEM IONIQ			\$31.30
1	BBOTLID H EMBLEM			\$38.00
2	REAR BUMPER REFLECTOR LH/RH		\$41.45	\$82.90
2	REAR BUMPER SIDE BRACKET LH/RH		\$55.80	\$111.60
				\$2,263.85
				\$452.77
				\$1,811.08

NA2 CLK
221612021 1605
PIL
3 DAYS
CHECK ITEM PHOTO
BY PAINT PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- the above vehicle. The final repair quantum will
- To display damaged part(s) during resurvey
- Surveyor appointed by the insurance company.

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Workshops

Date/Time: 21.06.2021 16:16

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4091071

JC NO.: 305474595


CUSTOMER VMS CUSTOMER NO. ADDRESS (R) (P) COUNT CARD NO.	COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (O)	
	REGN NO.: SHA1643M	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G2)	DATE/TIME IN 21.06.2021 11:00
	YR OF MANU. 02.07.2019	TARGET DATE
CHASSIS CODE KMHC851CVKU164510		COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 20.06.2021

NATURE: 3P 20.06.2021

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

1:

2:

Vehicle No.:

SHA1643M

CHIANG

Vehicle No.:

SHA1643M

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard