

China(PIP) JLI

COMFORTDELGRO ENGINEERING PTE LTD

Date: 21.06.2021

REPAIR ESTIMATE

Time: 17:08:56

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305474611
REGN NO : SHC1613P
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 05.07.2018
DATE/TIME IN : 21.06.2021 10:05
ACCIDENT DATE : 21.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	XB / DEF
0002 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	X R
0003 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	X SVL ✓ nec
0004 04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	- NEL
SUPP : LAMP ASSY-REAR FOG 1PC \$201.50						✓ cra
SUPP: NUMBER PLATE REAR 1PC \$50(SN)						✓ cra
SUB-TOTAL :						796.12

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30
SUB-TOTAL :		780.00	

TOTAL : 1,576.12

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

Mani
NAZ LKK
21/6/2021 1620
PIP
2 DAYS
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 21.06.2021 17:06

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4091094


JC NO.: 305474611

OWNER	REGN NO.: SHC1613P	MILEAGE
AS COMFORT TRANSPORTATION PTE LTD	MAKE : HYUNDAI	FUEL
OWNER NO. 7010045	MODEL IONIQ(G2)	E.....1/2.....F
RESS 383 SIN MING DRIVE	YR OF MANU. 05.07.2018	DATE/TIME IN 21.06.2021 10:05
Singapore SINGAPORE 575717	CHASSIS CODE KMHC851CVJU103494	TARGET DATE
(R) 65508755 (O)		COMPLETION DATE/TIME:
(P)		
COUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 21.06.2021
NATURE: 3P 21.06.2021

S/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

Exit Pass

No.: SHC1613P

JU CHINA

Vehicle No.:

SHC1613P

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard