

China (HP) JH 2

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 22.06.2021
Time: 15:13:24
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305474798
REGN NO : SHD6744G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 30.06.2016
DATE/TIME IN : 21.06.2021 11:35
ACCIDENT DATE : 15.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	BUMPER FRT COVER	1	1,052.20	20.00	841.76	✓ CRK
0002 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	✓ NEL
0003 04-01-0103-0639-G	BRACKET-FR BUMPER SIDE LH	1	44.80	20.00	35.84	?
0004 04-01-0103-0658-G	CAP ASSY-WHEEL HUB	1	214.20	20.00	171.36	✓ SK

SUB-TOTAL : 1,066.56

JOB NATURE

0000 PB	PANEL BEATING	300.00	560
0001 SP	SPRAYPAINT CHARGE	300.00	500

SUB-TOTAL : 600.00

TOTAL : 1,666.56

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

N42 CLK
22/6/2021 1635
LIS
2 DADJ
CHECK ITEM PHOTO
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

Team:	ARC Repair TP(CLS0)1	JOB CARD	Sales Order: 4091667	JC NO.: 305474798
OWNER	COMFORT TRANSPORTATION PTE LTD	REGN NO.: SHD6744G	MILEAGE	
IS	7010045	MAKE : HYUNDAI	FUEL	
OWNER NO.	383 SIN MING DRIVE	MODEL I-40	E.....1/2.....F	
RESS	Singapore SINGAPORE 575717	YR OF MANU. 30.06.2016	DATE/TIME IN 21.06.2021 11:35	
(R)	65508755	CHASSIS CODE KMHLB41UMGU091822	TARGET DATE	
(P)			COMPLETION DATE/TIME:	
OUNT CARD NO.				

JOB DESCRIPTION

Accident Date: 15.06.2021
NATURE: 3P 15.06.2021

S/NO LABOR CODE DESCRIPTION



OKED & PASSED OUT BY: _____

SERVICE ADVISOR	CUSTOMER'S SIGNATURE
-----------------	----------------------

edgement Slip	Exit Pass
No.: SHD6744G JU CHINA	Vehicle No.: SHD6744G
Service Advisor	Signature/Date
turned to Service Reception upon collection	Name of Service Advisor Date
	To be kept by Security Guard