



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                 |                            |  |
|--|---|-----------------|----------------------------|--|
| SOMPO INSURANCE SINGAPORE PL<br>50 RAFFLES PLACE #03-03<br>SINGAPORE LAND TOWERSINGAPORE 048623  |   |                 | Ref: CS/SMO21006947/Avf3n2 |  |
|  |   |                 | Date: 23/09/2021           |  |
|  |   |                 | Code: SMO                  |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |                 |                            |  |
| Insured Veh.   | SME 87U   | Veh. Inspected  | SMP 2768S                  |  |
| Policy No.   |   | Coverage (\$)   | 0.00                       |  |
| Claim No.  | CMTD2101884/THE   | Excess (\$)     | 0.00                       |  |
| Assign From  | GRACE TEO   | Assign Date     | 23/06/2021                 |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                 |                            |  |
| Make & Model   | MG HS   | c.c             | 1490                       |  |
| Engine No.   | HIDDEN  | Year of Reg.    | 2021                       |  |
| Chassis No.  | LSJA24U96MN025538   | Colour          | BLACK                      |  |
| Odometer   | 2223 KM   | Steering        | IN ORDER                   |  |
| Brakes   | IN ORDER  | Modification    | SPORTS RIM                 |  |
| General  | GOOD  |                 |                            |  |
| <b>3. Conditions of Tyres</b>  |   |                 |                            |  |
|  | Size  | Make            | Balance                    |  |
| R/H Front Tyre   | 235/50 R18  | MICHELIN        | 6 mm                       |  |
| L/H Front Tyre   | 235/50 R18  | MICHELIN        | 6 mm                       |  |
| R/H Rear Tyre  | 235/50 R18  | MICHELIN        | 6 mm                       |  |
| L/H Rear Tyre  | 235/50 R18  | MICHELIN        | 6 mm                       |  |
| <b>4. Description of Damages</b>   |   |                 |                            |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.<br>DAMAGES SEE DETAILS.  |   |                 |                            |  |
| <b>5. General Information</b>  |   |                 |                            |  |
| Accident Date  | 22/06/2021  | Inspection Date | 23/06/2021                 |  |
| Survey held at   | SM AUTOMOTIVE<br>BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883 |                 |                            |  |
| <b>5a. Remarks</b>   |   |                 |                            |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |                            |  |
| <b>5b. Estimate Days of Repair</b>   |   |                 |                            |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   |                 | <b>5 Working Days</b>      |  |