

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Layan Drive Singapore 508089  
Fax: 6546 8156

Our Job Ref No : 305474776  
Date : 25/06/21

## FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHA4707T

Date of Accident : 21.06.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


- The repair job shall bill to: NTUC SLJ6363T
- The finalized amount shall be:
  - Spare Parts after List discount
  - Labour Charges
  - Total for Part-By-Part Repair Cost
  - Lumpsum Repair (if applicable)
  - Total for Lumpsum repair cost after Less: 20%
  - Final Lumpsum Repair cost


\$1,400.00

\$1,400.00

- Estimated normal period for repairs: 2 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM T S  
Tel : 62148398  
Fax : 65468156

Signature :   
Name : NAZ  
Date : 8/7/2020

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: