

ASS. REC. BY:

NA2

REF:

ALG

Ju

PIF

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
LMS	R/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date _____ Person Contacted: _____

Veh No: SHD 44699 Yr Regn: 30 OCT 2019Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HYUNDAI IONIQ 1.6 CC 1,580Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 179,313 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM4C851CVLU187816Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / tyTOYO / YOKO or WESTLAKE br

Front

Rear

R/Bal. 5 mm R/Bal. 4 mmL/Bal. 5 mm L/Bal. 4 mmD.O.A. 22/6/2021 D.O.I. 23/6/2021Survey held at SHG LOYANGDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT

OFF-SIDE

NEAR-SIDE

The U/C / Chassis frame / Body Structure affected due to collision.

ALG PIF

Date / Time

Action / Instruction

Date/Time, File Pass 10?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return 10?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I: (\$ _____)