



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21006977/Uuf3n2	
			Date: 06/07/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 732Y	Veh. Inspected	SLD 9581S	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2101892/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	24/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	BMW 216D GRAN (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBA2E320205B45164	Colour	GREY	
Odometer	73369 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R17	BRIDGESTONE	7 mm	
L/H Front Tyre	205/55 R17	BRIDGESTONE	7 mm	
R/H Rear Tyre	205/55 R17	BRIDGESTONE	7 mm	
L/H Rear Tyre	205/55 R17	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/06/2021	Inspection Date	24/06/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	