

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/198R GS1 Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI21006980/Uqf3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Г	Date:	07/07/2021	
			C	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLC 5876Z	Veh. Inspected		SKV 3127C	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10010619/HA	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		24/06/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	NISSAN QASHQAI (A)	c.c		1197	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	SJNFEAJ11U1442879	Colour		RED	
	Odometer	65824 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R17	YOKOHAMA		6 mm	
	L/H Front Tyre	215/60 R17	YOKOHAMA		6 mm	
	R/H Rear Tyre	215/60 R17	YOKOHAMA		6 mm	
	L/H Rear Tyre	215/60 R17	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	22/06/2021	Inspection Date		30/06/2021	
	Survey held at	TAN LIM MOTOR PTE LTD				
		NO.1 DEFU LANE 6 SINGAPORE 539365				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: