



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21006989/Buf3e2	
			Date: 05/08/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 4513A	Veh. Inspected	SKV 6604Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/06/21/2044	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	24/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH 1.8	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JTDGG20W70J002915	Colour	BLACK
	Odometer	201634 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	MICHELIN	6 mm
	L/H Front Tyre	195/65 R15	MICHELIN	6 mm
	R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
	L/H Rear Tyre	195/65 R15	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/06/2021	Inspection Date	25/06/2021
	Survey held at	EDWIN GARAGE 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-295 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569535		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	