

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AUTO & GENERAL	INSURANCE (S) PL	Ref	:	CS3/AGI21007003/Vvf3e2	
		INSURANCE) 190 ENUE #03-01 SINGAPORE RESINGAPORE 239924	Dat	e:	06/07/2021	
			Cod	de:	AGI	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SDM 9449P	Veh. Inspected		SMV 1029S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10010589/KY	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		24/06/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA SHUTTLE 1.5G	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	GK82102542	Colour		GREY	
	Odometer	22422 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	YOKOHAMA		6 mm	
	L/H Front Tyre	185/60 R15	YOKOHAMA		6 mm	
	R/H Rear Tyre	185/60 R15	YOKOHAMA		6 mm	
	L/H Rear Tyre	185/60 R15	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	USTAINED DAMAGES AT THE REAR PORTION.				
5.	5. General Information					
	Accident Date	20/06/2021	Inspect Date / Time	е	24/06/2021 (04:00 PM)	
	Survey held at LKT GROUP PTE LTD					
	3006 UBI ROAD 1 #01-384 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408700					
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b. Estimate Days of Repair						
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				

Report Ref No. CS3/AGI21007003/Vvf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser