



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JACQUELINE LEONG			Ref: CC4/ASM21007007/Apa3q2 Date: 06/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLD 4757K	Veh. Inspected	SMJ 7936Y
	Policy No.	P1790540	Coverage (\$)	0.00
	Claim No.	S1M03CBM	Excess (\$)	0.00
	Assign From		Assign Date	24/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT	c.c	1317
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GK31342789	Colour	BLUE
	Odometer	38806 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	175/70 R14	DUNLOP	6 mm
	L/H Front Tyre	175/70 R14	DUNLOP	6 mm
	R/H Rear Tyre	175/70 R14	DUNLOP	6 mm
	L/H Rear Tyre	175/70 R14	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/06/2021	Inspection Date	24/06/2021
	Survey held at	SMARTONE AUTO PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		21 Working Days	