SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 24/06/2021 16:36 (SGT) Date of Accident 21/06/2021 07:30 (SGT) Exact Location of Accident Lor 14 Geylang, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBB95241

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner COOLWIN AIR-CON SERVICE ENGINEERING PTE LTD Company Reg No 5XXXX977L Email Address COOLWIN2013@GMAIL.COM Mobile Phone No (Phone) +65-67430068 Alternative Phone No (Office) +65-67430068

VEHICLE PARTICULARS

Manufacturer Nissan Model Nv350 Variant Exact purpose for which vehicle was being used at time of Employment accident Are you claiming under your own insurance policy for repair to your vehicle? No - Reporting only Vehicle Category Commercial vehicle Transmission Manual CC 2488

INSURANCE COMPANY

Name of Insurance Company Lonpac Insurance Bhd Type of Coverage ThirdPartyFireTheft Fleet Policy Policy Number Z21VC05007271 Cover Note Number

DRIVER

Name of Driver THANGAVEL BALAKRISHNAN Passport No/FIN GXXXX301X

Date Of Birth 03/04/1984 Occupation Outdoor Date Of Driving Pass 29/09/2014 Driving experience 6 YEARS AND 9 MONTHS Gender Mobile Number (Phone) +65-86897960 Alt. Phone Number Email Address COOLWIN2013@GMAIL.COM Address 33B GUILLEMARD RD Address complement Postcode 399700 Is the driver the policyholder? Nο If No. Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Hit and run / Vandalism / Damaged whilst parked Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Nο Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Nο **DETAILS OF POLICE ACTION** Was the accident reported to the police? Yes Police Station Name Geylang Neighbourhood Police Centre Police Station Phone No (Phone) +65-18008486999 Alt. Police Station Phone No (Fax) +65-68486799 Police Station Address 1 Cassia Link Singapore 397618 Was notice of intended Prosecution given? Nο If yes, against whom? CIRCUMSTANCES OF ACCIDENT PLS REFER TO THE POLICE REPORT:T/20210621/2032 ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Nο Was there any audio recorded? **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number UNKNOWN Vehicle Manufacturer Vehicle Model Vehicle Variant

NA / Unknown

Vehicle Colour
Vehicle Category

Name of Driver				_
Contact Number			 	_
Address			 	_
Address complement	 			_
Postcode				_
Insurance Company Name	 			_
Nature Of Damage				_
Details of property damaged in accident		 		_
No. Of Passenger (Including Driver)				_

SKETCH PLAN

IMPORTANT NOTICE

- Hease report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer , my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (I) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the clams:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (fv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Driver's Signature (if driver is not the policyholder) / Date & Time

24/06/21 Witnessed by Reporting Centre

Sketch Plan

14 GEGLANIG

PLS REFER TO TH	E-POLICE REPORT.T/20210621/2032
- Arenan - A	
Maria Maria Maria	
aration	
declare the foregoing particula	ars are true in every respect.
SON SERVICE	1
ANN ARP	- 23/06/2021 Sym 24/08
183	F Belin 23/06/2021 olyun 24/01
holder's Signature / Date &	Driver's Signature (# driver is not the policyholder) / Date Witnessed by Reporting Centre



T/20210621/2032

Police Station Of Origin: Geylang N.P.C 1 Cassia Link SINGAPORE 397618 Tel No: 1800-8486999

2 of 3 Report No. T/20210821/2032

CONTINUATION OF REPORT

Driver				0.000	11710	THOUSE THE STATE OF THE STATE O
Name	THANGAVEL BALA	KRISHNA	N	ID No).	G7774301X
Related Vehicle	GBB9524L (Van)			Conta	act No.	86897960
Hospital/Clinic	NIL			Class Drivin Licen Expin	g	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL		Date Disc		-	
No. of Days gran	ted Medical Leave	NIL	Degree o		NIL	


Brief Details.

On the above mentioned date, time and location, i discovered that my vehicle have unknown damages on the rear bumper. On 19/06/2021 at 2000hrs, i parked my vehicle on the said location and there was no unknown damages on the rear bumper.


I would also like to state that I do not have any dashboard camera on the vehicle.


















Police Station Of Origin: Geylang N.P.C 1 Cassia Link SINGAPORE 397618 Tel No: 1800-8486999 1 of 3 Report No. T/20210521/2032

	F A TRAFFIC		Lagar David No.	Station Diary No.		
Date/Time Report Made: 21/06/2021 12:43			Vide Report No.:	30		
Informat	nt's Particu	lars				
Name of	Informant:		Address: 33b guillemard road SINGAPO	ORE		
THANGAVEL BALAKRISHNAN ID Type / ID No.: FIN NO / G7774301X			Contact No.: Home/Office:	Mobile: 86897960		
National INDIAN		900 - 200	Email:			
Sex: Male	Age:	Date of Birth: 03/04/1984	Type of Informant: Driver	Le us si e LOshaal Name!		
Race:	14		Language:	Institution / School Name:		
Occupation: CONSTRUCTION WORKER		WORKER	Driving Licence Information: Class: 2B,3	Date of Expiry:		

Seneral Information Type of Accident:	Non-Injury Hit and Run	Drink Date/Time Drive: Accident: No 21/06/2021		Type of Location Car Park	
Location: LORONG 14	GEYLANG	Road Surface:		Road Speed Limit:	
Weather: Clear	veather.			T off a Malaymon	
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Light	
One Way Type of Colli Moving Vehi	sion: cle Against - Parked V			Anyone conveyed by ambulance: No	

Details of V	enicle invo		Madel	Color	Condition	No of Passenge
Vehicle No.	Туре	Make	Model	COIO	Slightly	0
GBB9524L	Van				Damaged	

Details of Person Involved	
Any Pedestrian Involved: No	Live Contribution Congrigation NA
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



T/20210621/2022

Police Station Of Origin: Geylang N.P.C 1 Cassia Link SINGAPORE 397618 Tel No: 1800-8486999

2 of 3 Report No. T/20210821/2032

CONTINUATION OF REPORT

Driver				2200	The state of	NAME OF THE OWNER OWNER OF THE OWNER OWNE
Name	THANGAVEL BALA	KRISHNA	N	ID No).	G7774301X
Related Vehicle	GBB9524L (Van)			Conta	act No.	86897960
Hospital/Clinic	NIL			Class Drivin Licen Expin	g	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL		Date Disc		-	
No. of Days gran	ted Medical Leave	NIL	Degree o		NIL	

Brief Details.

On the above mentioned date , time and location , i discovered that my vehicle have unknown damages on the rear bumper . On 19/06/2021 at 2000hrs , i parked my vehicle on the said location and there was no unknown damages on the rear bumper.

I would also like to state that I do not have any dashboard camera on the vehicle.





Police Station Of Origin: Geylang N.P.C 1 Cassia Link SINGAPORE 397618 Tel No: 1800-8486999 3 of 3 Report No. T/20210621/2032

CONTINUATION OF REPORT

ATL Y			101	A 112
100	F.D.1	U - 13	- 1-	2411

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Informant
Date/Time: 21/06/2021 12:43
Classification Of Case: