

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	CHINA TAIPING IN	ISURANCE (S) PTE LTD		Ref:	CS3/CTI20008597/Gtf3n2-1
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909		Date:	09/07/2021
				Code:	CTI
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJT 5461X	Veh. Inspected	ł	SMR 1811X
	Policy No.	DMPCSN30693719000	Coverage (\$)		0.00
	Claim No.	SNM20D202899/C02	Excess (\$)		0.00
	Assign From	JACQUELINE TAN	Assign Date		24/06/2021
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES-BENZ C200 AMG	c.c		1497
	Engine No.	HIDDEN	Year of Reg.		2019
	Chassis No.	WDD2053772F803385	Colour		WHITE
	Odometer	12986 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	245/40 R18	BRIDGESTONE		6 mm
	L/H Front Tyre	245/40 R18	BRIDGESTONE		6 mm
	R/H Rear Tyre	245/40 R18	BRIDGESTONE		6 mm
	L/H Rear Tyre	245/40 R18	BRIDGESTONE		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	17/08/2020	Inspection Dat	e	18/08/2020
	Survey held at	EM SOLUTION PTE LTD			
		160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
		OINOAI ONE 010122			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				