



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: YVONNE ANG			Ref: CS/ASM21007023/Evce2 Date: 30/07/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4971E	Veh. Inspected	XD 7790B	
Policy No.		Coverage (\$)	0.00	
Claim No.	S1M03CH9	Excess (\$)	0.00	
Assign From	PAY DANIEL	Assign Date	25/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	SCANIA P400	c.c	12742	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	YS2P8X40005321908	Colour	MULTI COLOUR	
Odometer	135009 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	315/80 R22.5	BRIDGESTONE	4 mm	
L/H Front Tyre	315/80 R22.5	BRIDGESTONE	4 mm	
R/H Rear Tyre	315/80 R22.5	BRIDGESTONE	4 mm	
L/H Rear Tyre	315/80 R22.5	BRIDGESTONE	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/06/2021	Inspection Date	12/07/2021	
Survey held at	10 BUROH ST #01-31/32/33 WEST CONNECT BUILDING			
Repairer	EM SOLUTION PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	