

106/11/13) wef
ASS. REC. BY: Paul

REF:

CS/AM 21007027/RV13

6534

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SBS 38504

at Workshop m/s SBS TRANSIT

of 550, BULKY BAYOC ST 23

Insured: SJN 1551C AM

Policy No. 1900083590

Claims No. 1118672076SG

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SBS 38504

Yr Regn:

2014 / OCT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo B4TL94LA

C.C. 9364

Colour:

MULTI

A/C: Insured / Std / NI / NA

Sp. Reading

494367

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

4V 384P924EA168818

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: M / S / Rim / STD A / Rim or

Tyre Size:

F:

275 / 70R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

23/06/21

D.O.I.

25/06/21

Survey held at

SBS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/7/21

Submit \$798.68 (un-confirmed)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 7/7/21-Typist

Days Of Repair: 1

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format : Merimen

Lump Sum / I.B.I: (\$

)

BUS REGISTRATION NUMBER:	SBS3850U
BUS TYPE:	WDD
DATE OF SURVEY:	

Acknowledge By _____

Insurer Co Name
AIG _____

Surveyor Name
RASUL _____

Signature _____

Date / Time 25/06/21 @ 1440

Contact No.: 90010068

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	653M
Vehicle No.:	SB53850U
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Jun 2021
Vehicle Make:	VOLVO
Vehicle Model:	B9TL 9.4L AUTO TURBO ABS
Primary Colour:	Multicolor
Manufacturing Year:	2014
Engine No.:	D9193200
Chassis No.:	YV354P924EA168818
Maximum Power Output:	-
Open Market Value:	\$479,149.00
Original Registration Date:	08 Oct 2014
First Registration Date:	08 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$0.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 27 Jun 2021

OK