

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305475214
Date : 28/06/21

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. : SHC8869Y CTPL

23.06.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG SMS9250G
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$2,500.00
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : [Signature]

Name : MS. LOKE YY

Tel : 62148355

Fax : 65468156

Signature : [Signature]

Name : NAZ LKK

Date : 12/7/2021

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC8869Y

Date: 25/06/2021

Make : HYUNDAI

Insurance: AIG

Model : I-40

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$1,052.20
10	FRT BUMPER CLIPS			\$22.00
1	FRT BUMPER BRACKET TOP LH			\$44.80
1	FRT FENDER LH			\$663.00
1	HEADLAMP LH			\$1,800.00
	SUB TOTAL		2,874.20	\$3,582.00
	LESS 20%			\$716.40
	DISCOUNTED TOTAL		2,299.36	\$2,865.60
	FRT FENDER ADVERTISEMENT LOGO LH			\$100.00
				Nett
				\$100.00
				Nett
	Labour Charge			
	PANEL BEATING			\$600.00
	SPRAY PAINTING CHARGE			\$600.00
	WIRING CHARGE			\$60.00
	TOTAL LABOUR			\$1,260.00
	ESTIMATE TOTAL			\$4,225.60

DEF
NEC
XSVC
KR
SCR

NEC
Nett
Nett

58 560
500 250
30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA2 LKK
25/6/2021 1705
LIS
3 DAYS
CHECK ITEM PHOTOS
AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: