

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / FPY WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CM /

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I.: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

) S + RS. SI

) Photos

) Others

TOTAL

* submit to insurance.

not Anthony
Lyle
25/6/11

FASTTECH AUTO PTE LTD
1 KAKI BUKIT AVE #01-48
S'PORE 417883 TEL 67457158

1/5 \$5600

VEHICLE No: GBC 40675

NETT ITEM 5 days.

1PC	REAR BACK DOOR N/S	Bad 500	1336	\$1,610.10	/
1PC	REAR BACK DOOR 'NV 200' EMBLEM N/S	neu	1470	\$205.30	/
1PC	REAR BACK DOOR REAR LOGO N/S	neu		\$66.80	/
1PC	REAR BACK DOOR OUTER HANDLE N/S	good		\$168.50	/
1PC	REAR BACK DOOR LOWER LOCK N/S	shotel / neu	135.20	\$299.30	/
1PC	REAR BACK DOOR INNER TRIM N/S	to 11	241.20	\$625.10	/
1SET	REAR BACK DOOR INNER TRIM CLIPS N/S	neu		\$25.00	/
1PC	REAR WIPER MOTOR	sent / neu	650.00	\$845.20	/
1PC	REAR WIPER ARM	neu		\$95.00	x
1PC	REAR BACK DOOR O/S	DD	910.90	\$1,615.10	/
1PC	REAR BACK DOOR 'DCI' EMBLEM O/S	neu		\$66.80	/
1PC	REAR BACK DOOR LOWER LOCK O/S	neu		\$299.30	x
1PC	REAR BACK DOOR INNER RUBBER O/S	twi	165.30	\$288.50	/
1PC	REAR BACK DOOR INNER TRIM O/S	11		\$605.10	/
1SET	REAR BACK DOOR INNER TRIM CLIPS O/S	11		\$30.00	x
1PC	REAR BUMPER	neu	485.90	\$822.30	/
2PCS	REAR BUMPER REFLECTORS @\$60.00	11		\$120.00	x
1PC	REAR BUMPER SPONGE	to 11	194.20	\$288.00	/
2PCS	REAR BUMPER SIDE HOLDERS @95.00	11		\$190.00	x
2PCS	TAILLAMPS @\$480.00	n / sent	282.10	\$960.00	120
1PC	REAR END PANEL	20 / sent	288.20	\$655.20	/
1PC	REAR END PANEL TOP GARNISH	twi	80.60	\$311.30	/
1PC	REAR END PANEL WEATHERSTRIP	twi	245.30	\$366.50	/
1PC	REAR FLOOR PANEL	R		\$1,420.00	x
				\$11,978.40	

S.NETT

1PC	REAR BACK DOOR GLASS SEALANT N/S	neu	\$50.00	40
1PC	70KM/H STICKER	neu	\$20.00	10
1PC	REAR BACK DOOR GLASS SEALANT O/S	neu	\$50.00	40
1PC	6 PAX STICKER	neu	\$20.00	10
1SET	REAR BUMPER REVERSE SENSOR	shotel	\$280.00	200
1SET	REAR BUMPER CLIPS	neu	\$30.00	/
1SET	REAR FLOOR PANEL INSULATOR	11	\$180.00	x

TO CHECK WIRING	\$80.00	20
TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX BOTH BACK DOOR GLASS	\$300.00	200
TO DISMANTLE & REFIX BOTH BACK DOOR MECHANISM	\$200.00	120
TO DISMANTLE & REFIX REAR EXHAUST	\$80.00	x
TO SPRAY RUST PROOFING	\$120.00	80

LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$1,500.00 000

\$1,500.00 700

TOTAL

\$16,468.40

9-5453.70

10%

9-4908.33

S.N - 330

L - 1770

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: