

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

Vehicle Number : SLC4848L
Vehicle Model : MER.BENZ CLA180
Accident Date : 23.06.2021
Original Reg Date : 23.05.2026

Date : 25.06.2021
Chassis : WDD1173422N321287
TP Ins. AXA

Xiao Tony.

ESTIMATE

SN	QTY	PARTS DESCRIPTION	UNIT PRICE	LIST PRICE
1	1 pc	FRONT DOOR LH <i>Dented</i>		1,896.30
2	1 pc	FRONT DOOR INNER TRIM LH <i>New</i>		895.60
3	1 pc	FRONT DOOR OUTER CHROME MOLDING <i>New</i>		325.80
4	1 pc	FRONT DOOR INNER LOCK LH <i>New</i>		398.70
5	1 pc	REAR DOOR LH <i>Distorted</i>		1,897.60
6	1 pc	REAR DOOR INNERTRIM LH <i>New</i>		896.30
7	1 pc	REAR DOOR STICKERS <i>New</i>		89.60
8	1 pc	REAR DOOR OUTER CHROME MOLDING <i>New</i>		325.60
9	1 pc	REAR DOOR INNER LOCK LH <i>Damaged</i>		396.50
10	1 pc	SIIDESKIRT LH <i>Crushed</i>		987.60
11	1 pc	SIIDE MIRROR ASSY LH <i>New</i>		956.30
12	1 pc	TAILAMP LH <i>New</i>		896.30
13	1 pc	REAR FENDER LH <i>Repair</i>		1,985.60
14	1 pc	REAR FENDER INNER COWLING LH <i>New</i>		198.60
15	1 pc	REAR BUMPER <i>New</i>		982.30
16	1 pc	REAR BUMPER RETAINER <i>New</i>		165.30
17	1 pc	REAR ABSORBER LH <i>New</i>		685.20
18	1 pc	REAR LOWER ARM LH <i>New</i>		572.30
19	1 pc	REAR UPPER ARM LH <i>New</i>		563.20
20	1 pc	REAR KNUCKLE ARM LH <i>New</i>		598.70
21	1 pc	REAR CONTROL ARM LH <i>New</i>		498.30
22	1 pc	REAR STABILIZER LINK LH <i>New</i>		165.30

subtotal **16,377.00**

Part disc 10% 1,637.70

Total **14,739.30**

6479.20

5831.28

Special Nett

1	1 set	Body Panel Joint Sealant <i>New</i>		120.00
2	1 set	REAR BUMPER CLIPS <i>New</i>		30.00

3	1 set	FRONT DOOR INNER TRIM CLIPS	2		30.00	x
4	1 set	REAR DOOR INNER TRIM CLIPS	1/2		30.00	x
5	1 set	REAR FENDER INNER COWLING CLIPS	1/2		30.00	x
6	1 set	SIDESKIRT CLIPS	1/2		30.00	/
7	1 set	WINDSCREEN SEALANT	1/2		80.00	x
8	1 PC	REAR SPORT RIM LH	1/2		1,250.00	800

830

Labour charge

Panel Beating		1,800.00	700
Spray painting		1,600.00	700
Check Wiring on tailamp		120.00	30
Anti rust and tuft coating		180.00	50
TO REMOVE / INSTALL WINDSCREEN		120.00	x
TO REMOVE / INSTALL UNDERCARRIAGE		250.00	200
TO PERFORM WHEEL ALIGNMENT		120.00	80
TO REMOVE / INSTALL FUEL TANK		200.00	x
Remove and install carpet and interior upholstery		150.00	50
Remove/install reverse sensor & distance settling		150.00	x

Grand Total \$ 21,029.30

1810

Person Incharge: JOHN
Direct Contact: 98287487
Email: ktmotorwerk@hotmail.com

Supplementary: 943.47

Total: 9414.75

1/5: 7.5K

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7.5K

REQUEST FOR SUPPLEMENTS PARTS

Vehicle No	SLC4848L	Date of Request	25.06.2021
Vehicle Model	MERCEDES CLA180	Number of Days to Extend (If any)	

S/N	Part Description	QTY	LIST PRICE
1	REAR DOOR WEATHERSTRIP LH	<i>New</i> 1	258.7 ✓
2	REAR DOOR SPEAKER LH	<i>New</i> 1	325.8 +
3	REAR DOOR GLASS REGULATOR LH	<i>Done</i> 1	789.6 ✓

1048.30

Supplementary: 943.47

CITY TYREAUTO PTE LTD
219 KAKI BUKIT AVE 1
SHUN LI INDUSTRIAL PARK
SINGAPORE 416044
TEL: 67466686
H/P: 85153676

Work Order: R003538
 License: SLC4848L
 Date: 24.6.21 18:02

Mercedes-Benz : 117 (CLA Class 2013-19) : with Code 485 (C/X)

Front : Left

Actual	Before	Specified Range
-0°46'	-0°46'	-1°17' -0°37'
0°00'	0°00'	
0°04'	0°04'	0°02' 0°12'
1°16'	1°16'	
0°30'	0°30'	
		-1°24' -0°24'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°46'	-0°46'	-1°17' -0°37'
0°00'	0°00'	
0°05'	0°05'	0°02' 0°12'
1°16'	1°16'	
0°30'	0°30'	
		-1°24' -0°24'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°01'	-0°01'	-0°24' 0°24'
0°00'	0°00'	-0°30' 0°30'
0°01'	0°01'	
0°03'	0°03'	0°04' 0°24'

Rear : Left

Actual	Before	Specified Range
1°07'	1°07'	
0°42'	0°42'	-0°04' 0°11'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°04'	-1°04'	
0°00'	0°00'	-0°04' 0°11'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
2°11'	2°11'	-0°30' 0°30'
0°42'	0°42'	0°00' 0°14'
0°21'	0°21'	-0°08' 0°08'